

Lathe Machining



Preface

What's New?

Getting Started

Open the Part to Machine

Create a Lathe Roughing Operation

Replay the Toolpath

Create a Lathe Grooving Operation

Create Lathe Profile Finishing Operation

Generate NC Code

Basic Tasks

Lathe Machining Operations

Longitudinal Roughing

Face Roughing

Parallel Contour Roughing

Recessing

Grooving

Profile Finishing

Groove Finishing

Threading

Sequential Machining

Local Information

Axial Machining Operations

Manufacturing Entities

Edit Lathe Tool on an Operation

Edit Lathe Tool in the Resource List

Edit Lathe Tool Assembly in the Resource List

Edit Lathe Insert in the Resource List

Auxiliary Operations

Verification, Simulation and Program Output

Part Operations, Programs and Processes

Advanced Tasks

Workbench Description

- Menu Bar

- Toolbars

- Specification Tree

Customizing

Reference Information

- Lathe Operations

- Cutter Compensation and Finish Operations

- Changing the Output Point

- Lathe Tool Assembly Conventions

- Actual Stock Computation

Glossary

Index

Preface

Lathe Machining easily defines NC programs dedicated to machining 3D cylindrical parts using 2-axis turning and drilling operations, for both horizontal and vertical spindle lathe machines.

Quick tool path definition is ensured thanks to an intuitive user interface based on graphic dialog boxes.

Tools can be easily created and integrated to tool catalogs. Tool path can be generated, simulated and analyzed.

Whole manufacturing process is covered from tool path definition to NC data generation thanks to an integrated postprocessor execution engine. Shop floor documentation is automatically created in HTML format.

Finally, associativity with Version 5 design products allows productive design change management.

Suitable for all kinds of cylindrical machined parts, Lathe Machining fits the needs of Fabrication & Assembly industry, as well as all industries where lathe machining techniques are involved.

It can be used in shop-floors as a stand-alone product for CAM-centric customers, who will particularly appreciate the product's ease-of-use and high level of manufacturing capabilities. Lathe Machining can be combined with DELMIA products for overall manufacturing process integration, simulation and optimization, particularly for bigger customers concerned by high quality and quick time-to-market.

Certain portions of this product contain elements subject to copyright owned by the following entities:

- © Copyright LightWork Design Ltd., all rights reserved.
- © Copyright Deneb Robotics Inc., all rights reserved.
- © Copyright Cenit, all rights reserved.
- © Copyright Intelligent Manufacturing Software, all rights reserved.
- © Copyright WALTER Informationssysteme GmbH, all rights reserved.
- © Copyright ICAM Technologies Corporation, all rights reserved.

What's New?

Sequential Machining

New: You can now create and manage a sequence of basic Go Standard, Go-Go, Go InDirv, Go Delta, and Follow tool motions in a single operation called [Sequential Machining](#).

General Functions

Enhanced: This product benefits from the [enhancements brought to the NC Manufacturing Infrastructure](#).

Getting Started

Before getting into the detailed instructions for using Lathe Machining, this tutorial is intended to give you a feel of what you can accomplish with the product.

It provides the following step-by-step scenario that shows you how to use some of the key functionalities.

- Open the Part to Machine
- Create a Lathe Roughing Operation
- Replay the Toolpath
- Create a Lathe Grooving Operation
- Create Lathe Profile Finishing Operation
- Generate NC Code

Open the Part to Machine



This first task shows you how to open a part, enter the Lathe Machining workbench and make basic modifications to the Part Operation.





1. Select File > Open then select the [Lathe01.CATPart](#) document.
2. Select NC Manufacturing > Lathe Machining from the Start menu.

The Lathe Machining workbench appears.

The part is displayed in the Setup Editor window along with the manufacturing specification tree.

3. Double click Part Operation.1 in the tree to display the Part Operation dialog box.
4. Click the Machine icon, then in the Machine Editor dialog box:
 - select the Horizontal Lathe Machine icon
 - make sure that the radial axis is set to X and the spindle axis is set to Z
 - click OK.
5. Set the tool change point in the Position tab page as shown below.
6. Click OK to confirm your modifications to the Part Operation.
7. Select Manufacturing Program.1 in the tree to make it the current entity.



To insert program entities such as machining operations, tools and auxiliary commands you can either:

- make the program current before clicking the *insert program entity* command
- click the *insert program entity* command then make the program current.



Create a Lathe Roughing Operation



This task shows you how to create a Longitudinal Roughing operation for machining part of the workpiece.

This operation will use the tool proposed by the program, so you just need to specify the geometry to be machined and set some of the machining parameters.



1. Select the Roughing icon .

A Roughing.1 entity along with a default tool is added to the program.


The Roughing dialog box appears directly at the Geometry tab page .


2. Click the red Stock area in the icon, then select the stock profile as shown.


Click OK in the Edge Selection toolbar to end your selection.

3. Click the red Part area in the icon, then select the part profile as shown.

Click OK in the Edge Selection toolbar to end your selection.



4. Select the Strategy tab page  and set the parameters as shown.



5. Click OK to create the operation.




Replay the Tool Path





This task shows you how to replay the tool path of the Roughing operation.





1. Select the Roughing operation in the tree then select the Replay Tool Path icon .

The Replay dialog box appears.

2. Choose the Continuous replay mode by means of the drop down icon .



3. Click the  button to position the tool at the start point of the operation.
4. Click the  button to start the replay. The tool moves along the computed trajectory.
5. Click OK to quit the replay mode.



Create a Lathe Grooving Operation



This task shows you how to create a Grooving operation to machine part of the workpiece.

You will specify the geometry to be machined, set some of the machining parameters and select a new tool.



Make sure that the Roughing operation is the current entity in the program.





1. Select the Grooving icon .

The Grooving dialog box appears directly at the Geometry page .

2. Click the red Stock area in the icon, then select the stock profile as shown.

3. Click the red Part area in the icon, then select the groove profile as shown.




4. Select the Strategy tab page  and check machining parameters. Set the Grooving Safety Angle to 10 degrees.

5. Select the Tool tab  in the Tool Assembly tab page.

- Enter a name of the new tool (for example, Grooving Tool).
- Double click the l2 (shank length 2) parameter in the icon, then enter 60mm in the Edit Parameter dialog box.
- Set the Max cutting depth Technology parameter to 80mm.

6. Click Replay in the dialog box to visually check the operation's tool path.



Click OK to exit the replay mode and return to the Grooving dialog box.

7. Click OK to create the operation.




Create a Lathe Profile Finishing Operation





This task shows you how to insert a Profile Finishing operation in the program.



1. Select the Profile Finishing icon .

The Profile Finishing dialog box appears directly at the Geometry page .

2. Select the red part in the sensitive icon then select the part profile.
3. Select the Strategy tab page  and set the Leading Safety Angle to 0 degrees.
4. Click Replay to replay the operation as described previously.



- Click OK to exit the replay mode and return to the Profile Finishing dialog box.
5. Click OK to create the operation in the program.



Generate NC Code



This task shows you how to generate NC code from the program. An APT source file will be generated in this example.


Before doing this task, double click the Part Operation entity in the tree and, in the dialog box that appears, click the Machine icon to access the Machine Editor dialog box. Make sure that you have selected a Horizontal lathe machine and that the desired NC data format is set to Axis (X, Y, Z).



1. Use the right mouse key on the Manufacturing Program.1 entity in the tree to select Generate NC Code Interactively.

The Save NC File dialog box appears.

2. Select the folder where you want the file to be saved and specify the name of the file.



3. Click Save to create the APT source file.



Here is an extract from the Apt source file that could be generated:

```
$$ -----  
$$ Generated on Tuesday, May 15, 2001 05:14:58 PM  
$$ -----  
$$ Manufacturing Program.1  
$$ Part Operation.1  
$$*CATIA0  
$$ Manufacturing Program.1  
$$ 1.00000 0.00000 0.00000 0.00000  
$$ 0.00000 1.00000 0.00000 0.00000  
$$ 0.00000 0.00000 1.00000 0.00000  
PARTNO PART TO BE MACHINED  
COOLNT/ON  
CUTCOM/OFF  
PPRINT OPERATION NAME : Lathe Tool Change.1  
$$ Start generation of : Lathe Tool Change.1  
TLAXIS/ 0.000000, 0.000000, 1.000000  
$$ TOOLCHANGEBEGINNING
```

```
RAPID
GOTO / 125.00000, 0.00000, 275.00000
CUTTER/ 5.000000
TOOLNO/0,TURN
$$ End of generation of : Lathe Tool Change.1
PPRINT OPERATION NAME : Roughing.1
$$ Start generation of : Roughing.1
FEDRAT/ 0.3000,MMPR
SPINDL/ 70.0000,RPM
GOTO / 107.02703, 0.00000, 257.00000
GOTO / 107.02703, 0.00000, 255.00000
...
FEDRAT/ 0.8000,MMPR
GOTO / 0.21213, 0.00000, 225.21213
$$ End of generation of : Roughing.1
CUTCOM/OFF
$$ ----- CUTCOM OFF END OF LATHE -----
PPRINT OPERATION NAME : Lathe Tool Change.2
$$ Start generation of : Lathe Tool Change.2
$$ TOOLCHANGEBEGINNING
RAPID
GOTO / 125.00000, 0.00000, 275.00000
CUTTER/ 1.200000
TOOLNO/0,TURN
$$ End of generation of : Lathe Tool Change.2
PPRINT OPERATION NAME : Grooving.1
$$ Start generation of : Grooving.1
FEDRAT/ 0.3000,MMPR
SPINDL/ 70.0000,RPM
GOTO / 108.20000, 0.00000, 111.70000
GOTO / 106.20000, 0.00000, 111.70000
...
RAPID
GOTO / 108.20000, 0.00000, 57.91213
$$ End of generation of : Grooving.1
CUTCOM/OFF
$$ ----- CUTCOM OFF END OF LATHE -----
PPRINT OPERATION NAME : Lathe Tool Change.3
$$ Start generation of : Lathe Tool Change.3
$$ TOOLCHANGEBEGINNING
RAPID
GOTO / 125.00000, 0.00000, 275.00000
CUTTER/ 5.000000
TOOLNO/0,TURN
$$ End of generation of : Lathe Tool Change.3
PPRINT OPERATION NAME : Profile Finishing.1
$$ Start generation of : Profile Finishing.1
FEDRAT/ 0.3000,MMPR
SPINDL/ 70.0000,RPM
GOTO / 27.12132, 0.00000, 224.94975
GOTO / 28.53553, 0.00000, 223.53553
...
FEDRAT/ 0.8000,MMPR
GOTO / 100.21213, 0.00000, 4.78787
$$ End of generation of : Profile Finishing.1
SPINDL/OFF
```

REWIND/0
END



Basic Tasks

The basic tasks you will perform with Lathe Machining involve creating, editing and managing machining operations and other entities of the NC manufacturing process.

Lathe Machining Operations

Axial Machining Operations

Manufacturing Entities

Auxiliary Operations

Verification, Simulation and Program Output

Part Operations, Programs and Processes

Lathe Machining Operations

The tasks in this section show you how to create lathe machining operations in your manufacturing program.



Create a **Roughing** operation:

Select the Roughing icon and choose the desired roughing mode. You can then select the part and stock geometry and specify the tool to be used. Specify machining parameters, feeds and speeds, and NC macros as needed.

Basic tasks illustrate the following roughing modes:

- **Longitudinal**
- **Face**
- **Parallel Contours.**



Create a **Recessing** operation:

Select the Recessing icon and choose the desired recessing mode. You can then select the part and stock geometry and specify the tool to be used. Specify machining parameters, feeds and speeds, and NC macros as needed.



Create a **Grooving** operation:

Select the Grooving icon then select the part and stock geometry and specify the tool to be used. Specify machining parameters, feeds and speeds, and NC macros as needed.



Create a **Profile Finishing** operation:

Select the Profile Finishing icon then select the part profile and specify the tool to be used. Specify machining parameters, feeds and speeds, and NC macros as needed.



Create a **Groove Finishing** operation:

Select the Groove Finishing icon then select the part geometry and specify the tool to be used. Specify machining parameters, feeds and speeds, and NC macros as needed.



Create a **Threading** operation:

Select the Threading icon and choose the desired thread type. You can then select the part geometry and specify the tool to be used. Specify machining parameters, feeds and speeds, and NC macros as needed.



Create a **Sequential Machining** operation:

Create and manage a sequence of basic Go Standard, Go-Go, Go InDirv, Go Delta, and Follow tool motions in a single operation.

Manage **Local Information**:

Assign local feedrates and local thicknesses to Profile Finishing and Groove Finishing operations.



Create a Longitudinal Roughing Operation



This task illustrates how to create a [Longitudinal Roughing operation](#) in the program.

To create the operation you must define:

- the [geometry](#) to be machined
- the [tool](#) that will be used
- the parameters of the [machining strategy](#)
- the [feedrates and spindle speeds](#)
- the [macros \(transition paths\)](#)



Open the [Lathe01.CATPart](#) document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.




1. Select the Roughing icon

A Roughing entity along with a default tool is added to the program.


The Roughing dialog box appears directly at the Geometry tab page

This tab page includes a sensitive icon to help you specify the geometry to be machined.



The part and stock of the icon are colored red indicating that this geometry is required. All other geometry is optional.


2. Click the red part in the icon then select the desired part profile in the 3D window. The Edge Selection toolbar appears to help you with contour selection:



The Auto-link command allows you to select a first element then the element to Navigate to in

order to complete the profile selection.


The Axial/Radial, Radial/Axial, and Direct commands are also useful for profile selection.




The part of the icon is now colored green indicating that this geometry is now defined.

3. Click the red stock in the icon then select the desired stock profile in the 3D window.
4. Double click **Thickness on Part** in the icon.

Set this value to 5mm in the Edit Parameter dialog box and click OK.


5. Select the Strategy tab page  to specify the main machining strategy parameters:
 - Roughing mode: **Longitudinal**
 - Orientation: **External**
 - Location: **Front**.




6. Double click **Max depth of cut** in the icon.

Set this value to 15mm in the Edit Parameter dialog box and click OK.


Other optional parameters can be set in the Options tab page (lead-in and so on).

A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. Please refer to [Edit the Tool of a Lathe Operation](#).

7. Select the Feeds and Speeds tab page  to specify the feedrates and spindle speeds for the operation. See [Feeds and Speeds for Roughing](#) for more information.

8. Select the Macros tab page  to specify the operation's transition paths (approach and retract motion, for example). See [Define Macros on a Lathe Operation](#) for an example.

Before accepting the operation, you should check its validity by [replaying the tool path](#).








9. Click OK to create the operation.



Create a Face Roughing Operation


This task shows how to insert a [Face Roughing operation](#) in the program.

To create the operation you must define:


- the [geometry](#) to be machined 
- the [tool](#) that will be used 
- the parameters of the [machining strategy](#) 
- the [feedrates and spindle speeds](#) 
- the [macros \(transition paths\)](#) 

Open the [Lathe01.CATPart](#) document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.

1. Select the Roughing icon 

The Roughing dialog box appears directly at the Geometry tab page .


This page includes a sensitive icon to help you specify the geometry to be machined.



The part and stock in the icon are colored red indicating that this geometry is required for defining the operation.

2. Click the red part in the icon then select the desired part profile in the 3D window. The part of the icon is now colored green indicating that this geometry is now defined.
3. Click the red stock in the icon then select the desired stock profile in the 3D window.
4. Double click **Thickness on Part** in the icon.

Set this value to 5mm in the Edit Parameter dialog box and click OK.


5. Select the Strategy tab page  to specify the main machining strategy parameters:



- Roughing mode: **Face**
- Orientation: **External**
- Location: **Front**.

6. Double click **Max depth of cut** in the icon.



Set this value to 10mm in the Edit Parameter dialog box and click OK.

7. In the Options tab page, set the lift-off distance to 1.5mm.




 A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. This is described in [Edit the Tool of a Lathe Operation](#).

8. Select the Feeds and Speeds tab page  to specify the feedrates and spindle speeds for the operation. See [Feeds and Speeds for Roughing](#) for more information.

 If you want to specify approach and retract motion for the operation, select the Macros tab page  to specify the desired transition paths. See [Define Macros on a Lathe Operation](#) for an example.

9. Check the validity of the operation by [replaying the tool path](#).

10. Click OK to create the operation.








Create a Parallel Contour Roughing Operation



This task shows how to insert a [Parallel Contour Roughing operation](#) in the program.

To create the operation you must define:

- the [geometry](#) to be machined 
- the [tool](#) that will be used 
- the parameters of the [machining strategy](#) 
- the [feedrates and spindle speeds](#) 
- the [macros \(transition paths\)](#) 



Open the [Lathe01.CATPart](#) document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.




1. Select the Roughing icon 

A Roughing entity along with a default tool is added to the program.

The Roughing dialog box appears directly at the Geometry tab page




This tab page includes a sensitive icon to help you specify the geometry to be machined.



The part and stock of the icon are colored red indicating that this geometry is required.

2. Click the red part in the icon, then select the desired part profile in the 3D window. Select the stock in the same way.

3. Select the Strategy tab page  to specify the main machining strategy parameters:



- Roughing mode: **Parallel Contour**
- Orientation: **External**
- Location: **Front**
- Machining direction: **To head stock**.



4. Double click **Axial depth of cut** in the icon.


Set this value to 3mm in the Edit Parameter dialog box and click OK.

Set **Radial depth of cut** to 3mm in the same way.

Other optional parameters can be set in the Options tab page (lead-in and so on).


 A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. This is described in [Edit the Tool of a Lathe Operation](#).

5. Select the Feeds and Speeds tab page  to specify the feedrates and spindle speeds for the operation. See [Feeds and Speeds for Roughing](#) for more information.
6. If you want to specify approach and retract motion for the operation, select the Macros tab page  to specify the desired transition paths. See [Define Macros on a Lathe Operation](#) for an example.





Before accepting the operation, you should check its validity by [replaying the tool path](#).








7. Click OK to create the operation.




Create a Recessing Operation

 This task shows how to insert a [Recessing operation](#) in the program.

To create the operation you must define:

- the [geometry](#) to be machined 
- the [tool](#) that will be used 
- the parameters of the [machining strategy](#) 
- the [feedrates and spindle speeds](#) 
- the [macros \(transition paths\)](#) 

 Open the [Lathe01.CATPart](#) document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.


 1. Select the Recessing icon .


A Recessing entity along with a default tool is added to the program.

The Recessing dialog box appears directly at the Geometry tab page



This tab page includes a sensitive icon to help you specify the geometry to be machined.



 The part and stock in the icon are colored red indicating that this geometry is required.

2. Click the red part in the icon then select the desired part profile in the 3D window.
Select the stock in the same way.

3. Select the Strategy tab page 


to specify the main machining strategy parameters:

- Recessing mode: **Zig zag**
- Orientation: **External**
- Machining direction: **To head stock**.

4. Double click **Max depth of cut** in the icon.

Set this value to 10mm in the Edit Parameter dialog box and click OK.

Other optional parameters can be set in the Options tab page (lead-in and so on).



Recessing mode:


Orientation:



Machining direction:

Part contouring

Under spindle axis machining



A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. This is described in [Edit the Tool of a Lathe Operation](#).

5. Select the Feeds and Speeds tab page  to specify the feedrates and spindle speeds for the operation. See [Feeds and Speeds for Recessing](#) for more information.
6. If you want to specify approach and retract motion for the operation, select the Macros tab page  to specify the desired transition paths. See [Define Macros on a Lathe Operation](#) for an example.



Before accepting the operation, you should check its validity by [replaying the tool path](#).






7. Click OK to create the operation.




Create a Grooving Operation

 This task shows how to insert a [Grooving operation](#) in the program.

To create the operation you must define:

- the [geometry](#) to be machined 
- the [tool](#) that will be used 
- the parameters of the [machining strategy](#) 
- the [feedrates and spindle speeds](#) 
- the [macros \(transition paths\)](#) 


 Open the [Lathe01.CATPart](#) document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.

 1. Select the Grooving icon .

The Grooving dialog box appears directly at the Geometry tab page





This page includes a sensitive icon to help you specify the geometry to be machined.


 The part and stock in the icon are colored red indicating that this geometry is required for defining the operation.


2. Click the red part in the icon, then select the desired part profile in the 3D window.

Select the stock in the same way.

 The part and stock of the icon are now colored green indicating that this geometry is now defined.





3. Select the Strategy tab page  to specify the main machining strategy parameters:
- Orientation: **External**
 - First plunge position: **Center**
 - Next plunges position: **To head stock**.





4. Double click **Max depth of cut** in the icon.

Set this value to 10mm in the Edit Parameter dialog box and click OK.

Other optional parameters can be set in the Options tab page (lead-in and so on).

 A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. This is described in [Edit the Tool of a Lathe Operation](#).

5. Select the Feeds and Speeds tab page  to specify the feedrates and spindle speeds for the operation. See [Feeds and Speeds for Grooving](#) for more information.

 You can add approach and retract motions to the operation in the Macros tab page . See [Define Macros on a Lathe Operation](#) for an example.

6. Check the validity of the operation by [replaying the tool path](#).

7. Click OK to create the operation.










Create a Profile Finishing Operation



This task shows how to insert a [Profile Finishing operation](#) in the program.

To create the operation you must define:

- the [geometry](#) to be machined 
- the [tool](#) that will be used 
- the parameters of the [machining strategy](#) 
- the [feedrates and spindle speeds](#) 
- the [macros \(transition paths\)](#) 




Open the [Lathe01.CATPart](#) document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.



1. Select the Profile Finishing icon




The Profile Finishing dialog box appears directly at the Geometry tab page .

This page includes a sensitive icon to help you specify the geometry to be machined.



The part in the icon is colored red indicating that this geometry is required for defining the operation.

2. Click the red part in the icon, then select the desired part profile in the 3D window.



In addition to the global offsets and thicknesses that you can assign to the selected profile, you can also add local offsets and thicknesses.

Right click the geometry to be assigned the local value, and select the Add Local Information contextual command. A dialog box appears allowing you to assign the desired local values.


It is possible to locally invert the machining direction.

Other contextual commands are available for analyzing and resetting local information.

Please refer to [Local Information](#) for more details.

The part of the icon is now colored green indicating that this geometry is now defined.





4. Select the Strategy tab page  to specify the main machining strategy parameters:


- Orientation: **External**
- Location: **Center**
- Select the **Recess machining** checkbox
- Machining direction is set automatically **To spindle**.

Note that you can locally invert machining directions using [Local Information](#) facilities.

Other optional parameters can be set in the Machining and Corner processing tab pages.



A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. This is described in [Edit the Tool of a Lathe Operation](#).

5. Select the Feeds and Speeds tab page  to specify the feedrates and spindle speeds for the operation. See [Feeds and Speeds for Profile Finishing](#) for more information.




In addition to the global feedrates that you can assign for the operation, you can also add local feedrates to portions of the profile.

Right click the geometry to be assigned the local value, and select the Add Local Information contextual command. A dialog box appears allowing you to assign the desired local values.

Other contextual commands are available for analyzing and resetting local information.

Please refer to [Local Information](#) for more details.

You can add approach and retract motions to the operation in the Macros tab page . See [Define Macros on a Lathe Operation](#) for an example.

6. Check the validity of the operation by [replaying the tool path](#).
7. Click OK to create the operation.








Create a Groove Finishing Operation



This task shows how to insert a [Groove Finishing operation](#) in the program.

To create the operation you must define:

- the [geometry](#) to be machined 
- the [tool](#) that will be used 
- the parameters of the [machining strategy](#) 
- the [feedrates and spindle speeds](#) 
- the [macros \(transition paths\)](#) 




Open the [Lathe01.CATPart](#) document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.



1. Select the Groove Finishing icon



A Groove Finishing entity along with a default tool is added to the program.


The Groove Finishing dialog box appears directly at the Geometry tab page .

This tab page includes a sensitive icon to help you specify the geometry to be machined.

The part in the icon is colored red indicating that this geometry is required.



2. Click the red part in the icon then select the desired part profile in the 3D window.



In addition to the global offsets and thicknesses that you can assign to the selected profile, you can also add local offsets and thicknesses.

Right click the geometry to be assigned the local value, and select the Add Local Information contextual command. A dialog box appears allowing you to assign the desired local values.

Other contextual commands are available for analyzing and resetting local information.

Please refer to [Local Information](#) for more details.


3. Select the Strategy tab page





to specify the main machining strategy parameters:

- Orientation: **External**
- Machining direction: **To head stock**
- Contouring for outside corners: **Circular**.

Other optional parameters can be set in the Machining and Corner processing tab pages.



 A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. This is described in [Edit the Tool of a Lathe Operation](#).


4. Select the Feeds and Speeds tab page  to specify the feedrates and spindle speeds for the operation. See [Feeds and Speeds for Finish Grooving](#) for more information.


In addition to the global feedrates that you can assign for the operation, you can also add local feedrates to portions of the profile.

Right click the geometry to be assigned the local value, and select the Add Local Information contextual command. A dialog box appears allowing you to assign the desired local values.

Other contextual commands are available for analyzing and resetting local information.

Please refer to [Local Information](#) for more details.

5. Select the Macros tab page  to specify the operation's transition paths (approach and retract motion, for example). See [Define Macros on a Lathe Operation](#) for an example.

 Before accepting the operation, you should check its validity by [replaying the tool path](#).






6. Click OK to create the operation.



Create a Threading Operation

This task shows how to insert a **Threading operation** in the program.

To create the operation you must define:

- the **geometry** to be machined 
- the **tool** that will be used 
- the parameters of the **machining strategy** 
- the **feedrates and spindle speeds** 
- the **macros (transition paths)** 

Open the **Lathe01.CATPart** document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.

1. Select the Threading icon 

A Threading entity along with a default tool is added to the program.


The Threading dialog box appears directly at the Geometry tab page



This tab page includes a sensitive icon to help you specify the geometry to be machined.

The part in the icon is colored red indicating that this geometry is required.

2. Click the red part in the icon then select the desired part profile in the 3D window.
3. Double click Length in the icon then specify the desired length of threading in the Edit Parameters dialog box that appears.




4. Select the Strategy tab page 

to specify the main machining parameters that are organized in three tabs: Thread, Strategy and Options.

Set the following values in the Thread tab:



- Profile: **Other**
- Orientation: **External**
- Location: **Front**
- Thread unit: **Pitch**
- Number of threads: **1**
- Thread depth: **10mm**
- Thread pitch: **10mm**.

Other optional parameters can be set in the Strategy and Options tabs.





5. If you want to generate CYCLE statements, you must select the **Output CYCLE syntax** checkbox in the Options tab and set the **Syntax Used** option to Yes in the NC Output generation dialog box.

Otherwise, GOTO statements will be generated.

 A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. This is described in [Edit the Tool of a Lathe Operation](#).

6. Select the Feeds and Speeds tab page  to specify the machining spindle speed for threading.

7. Select the Macros tab page  to specify the operation's transition paths (approach and retract motion, for example). See [Define Macros on a Lathe Operation](#) for an example.

 Before accepting the operation, you should check its validity by [replaying the tool path](#).

8. Click OK to create the operation.



Example of output

If your PP table is customized with the following statement for Lathe Threading operations:

```
CYCLE/THREAD, %MFG_THREAD_PITCH
```

A typical NC data output is as follows:

```
CYCLE/THREAD, 10.000000
```

The parameters available for PP word syntaxes for this type of operation are described in the [NC_LATHE_THREADING](#) section of the [Manufacturing Infrastructure User's Guide](#).







Create a Sequential Machining Operation



This task illustrates how to create a [Sequential Machining operation](#) in the program.

To create the operation you must define:

- the list of motions making up the operation 
- the [tool](#) that will be used 
- the [feedrates and spindle speeds](#) 
- the [macros \(transition paths\)](#) 




Open the [Lathe01.CATPart](#) document, then select NC Manufacturing > Lathe Machining from the Start menu. Make the Manufacturing Program current in the specification tree.




1. Select the Sequential Machining icon 

A Sequential Machining entity along with a default tool is added to the program.

The dialog box appears directly at the List of Motions tab page 




The first motion must be a Go motion to a point or a Go motion with two check elements.


2. Select the Go icon 

The dialog box for defining the first motion appears.

In the Geometry tab:


- Successively select the two check elements in the dialog box then the desired check elements in the 3D view.
- Set the first and second check modes **To a curve**.
- Set a thickness on the first check element to 2mm.
- Click OK to define the motion.



3. Select the Go icon  again to define the second motion.


In the Geometry tab:

- Select a check element in the dialog box then the desired check element in the 3D view.
- Set the check mode to **Past a curve**.
- Set a thickness on the check element to 5mm.
- Click OK to define the motion.

4. Select the Go InDirv icon .

In the Geometry tab:


- Select the drive direction in the dialog box then the desired linear element in the 3D view.
- Set the check mode to **To a curve**.
- Click OK to define the motion.




5. Select the Follow icon .

In the Geometry tab:

- Select the drive curve in the dialog box then the desired drive element in the 3D view.
- Set the check mode to **On a curve**.
- Click OK to define the motion.





6. Select the PP word icon , then specify a PP word in the dialog box that appears (DELAY/5, for example).


7. Select the Go Delta icon .



In the Geometry tab:

- Set the check mode to **Line and distance**.
- Select the delta element in the dialog box then the desired linear element in the 3D view.
- Enter a distance.
- Click OK to define the motion.




 Other optional parameters can be set in the Strategy tab page for each of the motions.




 A tool is proposed by default when you want to create a machining operation. If the proposed tool is not suitable, just select the Tool tab page  to specify the tool you want to use. Please refer to [Edit the Tool of a Lathe Operation](#).

8. Select the Feeds and Speeds tab page  to specify the feedrates and spindle speeds for the operation. See [Feeds and Speeds for Roughing](#) for more information.

9. Select the Macros tab page  to specify the operation's transition paths (approach and retract motion, for example). See [Define Macros on a Lathe Operation](#) for an example.


Before accepting the operation, you should check its validity by [replaying the tool path](#).





10. Click OK to create the operation.




Manage Local Information

 This task illustrates how to manage Local Information (local feedrates and thicknesses) on a Profile Finishing or Groove Finishing operation.

To create Local Information, you must define the geometry to be machined .


 Create a Profile Finishing operation in the program.

In the Profile Finishing dialog box that appears, select the Geometry tab page .



Local Information can be added on lines, arcs and curves if they are part of a finished profile. Click the red part in the icon then select the desired finish profile in the 3D window.





To create or edit local information

To add local information on an element, right click on it and select "Add Local Information" in the contextual menu.


To edit Local Information from an element, right click on it and select "Edit Local Information" in the contextual menu.

In both cases, set the information you want and validate with "OK".

To copy the local information of an element and paste it on another element of the finish profile, right click on it and select "Copy Local Information" in the contextual menu, then right click on the target element and select "Paste Local Information".

In the Local Information Browser, you can edit local information by double clicking on the row of the list you are interested in.

To copy local information from an element and paste it on another element of the finished profile, select an element in the list of the Local Information Browser and select the information you want to copy in the right-frame. Then click "Paste on..." and select the target element.

 Local information is associated to the selected profile and is supported by that profile. If you delete the profile, the associated information is also deleted.

To view local information

To browse local information on a finished body, right click on an element of the finished body or on the representation of the Part Body in the Geometry tab, then select "Browse Local Information".

In the Local Information Browser, you can see on the 3D view of the finished body defined local information by clicking on the column header.


To remove local information

To remove Local Information from an element, right click on it and select "Remove Local Information" in the contextual menu.

In the Local Information Browser, click on the local information you want to delete and click Remove.

Options for Inverted Element (for Profile Finishing only)

The inversion of elements is possible for Profile Finishing operations. This is illustrated in the figure below:




In the Strategy tab page, click on the Local Invert tab.

To machine part with inverted elements, several strategies are available:

- **None:** the profile is machined with inverted ways of machining.
- **Thickness:** a given thickness is let on inverted element and the remaining material is removed when the inverted element is machined again.
- **Overlap:** a given length of an element is machined twice when the profile is machined and then when inverted elements are machined. In this case, you can choose to machine inverted elements first or later.

The lift-off can be linear or circular as specified in the Machining tab.





Axial Machining Operations

The tasks for creating axial machining operations are documented in the *Prismatic Machining User's Guide*.

Spot Drilling Operation



Create a Spot Drilling Operation: Select the Spot Drilling icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.

Drilling Operations



Create a Drilling Operation: Select the Drilling icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Drilling Dwell Delay Operation: Select the Drilling Dwell Delay icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Drilling Deep Hole Operation: Select the Drilling Deep Hole icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Drilling Break Chips Operation: Select the Drilling Break Chips icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.

Hole Finishing Operations



Create a Reaming Operation: Select the Reaming icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Counterboring Operation: Select the Counterboring icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.

Boring Operations



Create a Boring Operation: Select the Boring icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Boring Spindle Stop Operation: Select the Boring Spindle Stop icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Boring and Chamfering Operation: Select the Boring and Chamfering icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Back Boring Operation: Select the Back Boring icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.

Threading Operations



Create a Tapping Operation: Select the Tapping icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Reverse Threading Operation: Select the Reverse Threading icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Thread without Tap Head Operation: Select the Thread without Tap Head icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Thread Milling Operation: Select the Thread Milling icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.

Countersinking and Chamfering Operations



Create a Countersinking Operation: Select the Countersinking icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Chamfering Two Sides Operation: Select the Chamfering Two Sides icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.

T-Slotting and Circular Milling



Create a T-Slotting Operation: Select the T-Slotting icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros and feeds and speeds as needed.



Create a Circular Milling Operation: Select the Circular Milling icon then select the hole or hole pattern to be machined and specify the tool to be used. Specify machining strategy parameters, macros, and feeds and speeds as needed.



Managing Manufacturing Entities

Tasks involving manufacturing entities that are specific to the Lathe Machining product can be found in this section.

- [Edit the Tool of a Lathe Machining Operations](#)
- [Edit a Lathe Tool in the Resource List](#)
- [Edit a Lathe Tool Assembly in the Resource List](#)
- [Edit a Lathe Insert in the Resource List](#)

The tasks for creating and managing specific entities of the NC manufacturing environment are documented in the *NC Manufacturing Infrastructure User's Guide*.

Edit the Tool of a Milling or Drilling Operation: Double click the machining operation in the program and select the Tool tab page to edit the characteristics or search for a new tool.

Edit a Mill or Drill Tool in the Resource List: Double click a tool referenced in the resource list and edit the characteristics in the Tool Definition dialog box.

Edit a Mill or Drill Tool Assembly in the Resource List: Double click a tool assembly referenced in the resource list and edit the characteristics in the Tool Assembly Definition dialog box.

Specify Tool Compensation Information: Double click a tool referenced in the program or resource list and specify the tool compensation information in the Compensation tab page of the Tool Definition dialog box .

Create and Use Machining Patterns: Select Insert > Machining Feature > Machining Pattern then select a pattern of holes to be machined.

Feature Based Programming: Select a feature using the Manufacturing view and create operations based on this feature.


Define Macros on a Lathe Machining Operation: Select the Macros tab page when creating or editing a lathe machining operation, then specify the transition paths of the macros to be used in the operation.

Define Macros on an Axial Machining Operation: Select the Macros tab page when creating or editing an axial machining operation, then specify the transition paths of the macros to be used in the operation.

Manage the Status of Manufacturing Entities: Use the status lights to know whether or not your operation is correctly defined.




Edit the Tool of a Lathe Machining Operation

 This task shows you how to edit the tool of a lathe machining operation.

A machining operation always has a tool assigned to it (default tool, for example).

You can modify this tool in several ways:

- edit its characteristics, thereby [creating a new tool](#)
- replace it by [selecting another tool that is already used in the document](#)
- replace it by [selecting another tool by means of a query](#).

 1. Double click the operation in the program, then select the Tool tab page.

2. To create a new tool:

If you want to change tool type, select the icon corresponding to the desired tool type.


In this case the corresponding tool representation appears in the 2D viewer.

- Double click the geometric parameter that you want to modify in the 2D viewer, then enter the desired value in the Edit Parameters dialog box that appears.

Modify other parameters in the same way.

The tool representation is updated to take the new values into account.

- Click More to expand the dialog box to access all the tool's parameters. Modify the values as desired.
- Enter a name for the new tool.




3. To select a tool that is already used in the document:

- Select the button opposite Name.
- Select the desired tool from the list of tools already used in your document.
- The tool representation is displayed in the 2D viewer. It can be edited as described above.

4. To select another tool by means of a query:

- Click the **Select a tool with query** icon opposite Name. The Search Tool dialog box appears.



- Use the **Look in** combo to specify where you want to search for the tool:
 - in the current document,
 - in a tool catalog
 - in an external tool database such as the [Walter TDM \(Tool Data Management\)](#) or [CATIA Version 4 Manufacturing database](#)
 - in a [Feeds and Speeds catalog](#).
- If you want to change tool type, select the icon corresponding to the desired tool.
- You can do a quick search in the **Simple** tab page by means of a character string on the tool name. The tools meeting the simple search criteria are listed.
- Select the desired tool from the list and click OK. The tool representation is displayed in the 2D viewer. It can be edited as described above.



You can search a tool using finer constraints by selecting the **Advanced** tab page.

The example below shows the result of a search for a right hand tool with shank width of 15mm or more in the catalog ToolsSampleLathe.

Search Tool

Look in: ToolsSampleLathe

Simple **Advanced**

Search with criteria:
Hand style == Right hand
Shank width >= 15

Delete Clear all

Attribute: Condition: Value:
Shank width >= 15

Description code	Tool number	Comment	Name	Shank width	Sh
------------------	-------------	---------	------	-------------	----

1 Tool found

OK Cancel

Technical drawing dimensions:
 $b = 20\text{mm}$
 $h = 20\text{mm}$
 $f = 25\text{mm}$
 $l_2 = 40\text{mm}$
 $l_1 = 80\text{mm}$
 $K_r = 93\text{deg}$

5. Click OK to confirm using this new tool in the operation.



Edit a Lathe Tool in the Resource List



This task shows you how to edit a lathe tool that is already used in your document.




1. To edit a tool in the resource list either double click it or right click it and select the **Definition** contextual command.

The Tool Definition dialog box is displayed allowing you to edit the tool's geometric, technological, and compensation characteristics.

2. If needed, enter a new name for the tool.

You can also assign a comment.

3. Click More to expand the dialog box to access the Geometry, Technology, and Compensation tab pages.



4. You can specify the tool geometry in two ways:
 - double click a parameter in the large tool icon and enter the desired value in the Edit Parameter dialog box that appears
 - or enter the desired values in the **Geometry** tab page.

The icon representation of the tool is updated with these values.


5. Click the **Technology** tab and enter the desired values for the tool's technological parameters.

6. If tool compensation is required, click the **Compensation** tab.

You can either edit an existing compensation site or add another site, if other sites are proposed.

Geometry	Technology	Compensation
Hand style :	Left hand	
Holder capability :	Surface	
Kappa R (Kr):	95deg	
Insert angle (a):	80deg	
Insert length (l):	6.45mm	
Clearance angle :	7deg	
Shank cut width (f):	16mm	
Shank height (h):	12mm	
Shank length 1 (l1):	80mm	
Shank length 2 (l2):	18mm	
Shank width (b):	12mm	

Geometry	Technology	Compensation
Max machining length :	0mm	
Max life time :	0s	
Coolant syntax :		
Weight syntax :		
Trailing angle :	90deg	
Leading angle :	90deg	
Max rec. depth :	1000mm	



7. Right click the desired line to either edit or add tool compensation data.

The Compensation Definition dialog box appears.

8. Enter the desired values for the tool's compensation sites.

See [Specify Tool Compensation](#) for more information.

9. Click OK to accept the modifications made to the tool.

A user representation (CATPart) can be assigned to the tool by the contextual command in the Resource List.



Edit a Lathe Tool Assembly in the Resource List



This task shows you how to edit a tool assembly that is already used in your document.



1. To edit a tool assembly in the resource list either double click it or right click it and select the **Definition** contextual command.

The Tool Assembly Definition dialog box is displayed allowing you to edit the tool assembly's geometric and technological characteristics.

2. If needed, enter a new name for the tool assembly.

You can also assign a comment.

3. If needed, use the spinner to change the Tool number.

4. Click More to expand the dialog box to access the Geometry and Technology tab pages.

Tool Assembly Definition

Name : Lathe Assembly.1

Comment :

Tool number : 0


Setup angle : 0deg

More >>

OK Cancel


5. You can specify the tool assembly geometry in two ways:

- double click a parameter in the large tool assembly icon and enter the desired value in the Edit Parameter dialog box that appears
- or enter the desired values in the **Geometry** tab page.



The screenshot shows the 'Edit Parameter' dialog box with the 'Geometry' tab selected. It contains three input fields for dimensions: 'Set X (DX):' with a value of '0mm', 'Set Y (DY):' with a value of '0mm', and 'Set Z (DZ):' with a value of '0mm'. Each field has a small up/down arrow icon to its right. Below these fields is a checkbox labeled 'Tool inverted' which is currently unchecked.

6. Click the **Technology** tab and enter the desired values for the tool assembly's technological parameters.



The screenshot shows the 'Edit Parameter' dialog box with the 'Technology' tab selected. It contains four input fields for technological parameters: 'Number of components :', 'MFG_OUTP_PREF_1 :', 'MFG_OUTP_PREF_2 :', and 'MFG_OUTP_PREF_3 :'. The first field has a value of '1' and a small up/down arrow icon. The other three fields have a value of 'None' and a small downward arrow icon.

7. Click OK to accept the modifications made to the tool assembly.



A user representation (CATPart) can be assigned to the tool assembly by the contextual command in the Resource List.





Edit a Lathe Insert in the Resource List



This task shows you how to edit a lathe insert that is already used in your document.



1. To edit a lathe insert in the resource list either double click it or right click it and select the **Definition** contextual command.


The Insert Definition dialog box is displayed allowing you to edit the lathe insert's characteristics.

2. If needed, enter a new name for the lathe insert.

You can also assign a comment.

3. If needed, use the spinner to change the Tool number.

4. Click More to expand the dialog box to access the Geometry and Technology tab pages.



5. You can specify the lathe insert geometry in two ways:

- double click a parameter in the large lathe insert icon and enter the desired value in the Edit Parameter dialog box that appears
- or enter the desired values in the **Geometry** tab page.

Geometry	Technology	Feeds & Speeds
Height (l):	6mm	
Insert width (la):	3mm	
Bottom angle (b):	0deg	
Left flank angle (a1):	2.5deg	
Right flank angle (a2):	2.5deg	
Left nose radius (r1):	1.2mm	
Right nose radius (r2):	1.2mm	
Thickness (s):	2.5mm	
Clearance angle :	6deg	

6. Click the **Technology** tab and enter the desired values for the lathe insert's technological parameters.

Geometry	Technology	Feeds & Speeds
Machining quality :	Either	
Material :	Other	
Cutting length (Lc):	0mm	

7. Click the **Feeds and Speeds** tab and enter the desired values for the lathe insert's feed and speed parameters.

Geometry	Technology	Feeds & Speeds
Finishing cutting speed :	0mm_mn	
Finishing feed/tooth :	0mm_turn	
Roughing cutting speed :	0mm_mn	
Roughing feed/tooth :	0mm_turn	
MFG_PP_ROUGH :	0mm	
MFG_VC_ECROUTAGE :	0mm_mn	
MFG_SZ_ECROUTAGE :	0mm_turn	
MFG_PP_ECROUTAGE :	0mm	

8. Click OK to accept the modifications made to the lathe insert.

A user representation (CATPart) can be assigned to the lathe insert by the contextual command in the Resource List.





Auxiliary Operations

The tasks for inserting auxiliary operations in the program are documented in the *NC Manufacturing Infrastructure User's Guide*.



Insert Tool Change: Select the Tool Change icon then select the tool type to be referenced in the tool change.



Insert Machining Axis System or Origin: Select the Machining Axis or Origin icon then specify the characteristics of the machining axis system or origin.



Insert PP Instruction: Select the PP Instruction icon then enter the syntax of the PP instruction.



Insert Copy Transformation Instruction: Select the reference operation then select the Copy Transformation icon. You can then specify the number of copies and the characteristics of the transformation.



Verification, Simulation and Program Output

The tasks for using capabilities such as tool path verification, material removal simulation, and production of NC output data are documented in the *NC Manufacturing Infrastructure User's Guide*.



Replay Tool Path: Select the Tool Path Replay icon then specify the display options for an animated tool path display of the manufacturing program of machining operation.



Simulate Material Removal (P2 functionality): Select the desired icon in the Tool Path Replay dialog box to run a material removal simulation either in Photo or Video mode.



Generate APT Source Code in Batch Mode: Select the Generate NC Code in Batch Mode icon then select the manufacturing program to be processed and define the APT source processing options.

Generate NC Code in Batch Mode: Select the Generate NC Code in Batch Mode icon then select the manufacturing program to be processed and define the NC code processing options.

Generate Clfile Code in Batch Mode: Select the Generate NC Code in Batch Mode icon then select the manufacturing program to be processed and define the Clfile processing options.

Generate a CGR File in Batch Mode (P2 functionality): Select the Generate NC Code in Batch Mode icon then select the manufacturing program to be processed and define the CGR file processing options.



Generate APT Source Code in Interactive Mode: Select the Generate NC Code Interactively icon to generate APT source code for the current manufacturing program.



Generate Documentation: Select the Generate Documentation icon to produce shop floor documentation in HTML format.

Import an APT Source into the Program: Select the APT Import contextual command to insert an existing APT source into the current manufacturing program.



Part Operations, Programs and Processes

The tasks for creating and managing Part Operations, Manufacturing Programs and Machining Processes are documented in the *NC Manufacturing Infrastructure User's Guide*.



Create and Edit a Part Operation: Select the Part Operation icon then specify the entities to be referenced by the part operation: machine tool, machining axis system, tool change point, part set up, and so on.



Create and Edit a Manufacturing Program: Select the Manufacturing Program icon to add a program to the current part operation then insert all necessary program entities: machining operations, tool changes, PP instructions, and so on.



Create a Machining Process (P2 Functionality): Select the Machining Process icon to create a machining process, which will be stored in a CATProcess document and then as a catalog component.



Apply a Machining Process (P2 Functionality): Select the Open Catalog icon to access the machining process to be applied to selected geometry.



Advanced Tasks


Tasks dealing with the following NC Manufacturing functionalities are described in the *NC Manufacturing Infrastructure User's Guide*.

Design Changes
Set Up and Part Positioning

Workbench Description

This section contains the description of the menu commands and icon toolbars that are specific to the Lathe Machining workbench.

- Menu Bar
- Toolbars
- Specification Tree



Lathe Machining Menu Bar


The menu commands that are specific to Lathe Machining are described below.



Tasks corresponding to general menu commands are described in the *CATIA Version 5 Infrastructure User's Guide*.

Tasks corresponding to menu commands that are common to all NC Manufacturing products are described in the *NC Manufacturing Infrastructure User's Guide*.

Insert Menu



Insert > Machining Operations

Command...

Roughing

Description...


Create a Longitudinal Roughing Operation

Create a Parallel Contour Roughing Operation

Create a Face Roughing Operation

Grooving

Create Grooving Operation




Recessing
Profile Finishing
Groove Finishing
Threading
Sequential Machining

Axial Machining Operations

Create Recessing Operation
Create a Profile Finishing Operation
Create a Groove Finishing Operation
Create a Threading Operation
Create a Sequential Machining Operation

Create Axial Machining Operations

Insert > Auxiliary Operations > Lathe Tool Change



Description...

Allows inserting lathe tool changes in the program.



Lathe Machining Toolbars

The Lathe Machining workbench includes a number of icon toolbars, some of which are common to all NC workbenches and some of which are specific to Lathe Machining. The common toolbars are described in the [Toolbars section of the NC Manufacturing Infrastructure User's Guide](#).

The following toolbar is specific to the Lathe Machining workbench.



It contains commands to create and edit lathe machining operations as follows.



Create a [Roughing](#) operation.

Basic tasks illustrate the following roughing modes:

- [Longitudinal](#)
- [Face](#)
- [Parallel Contours](#).



Create a [Recessing](#) operation.



Create a [Grooving](#) operation.



Create a [Profile Finishing](#) operation.



Create a [Groove Finishing](#) operation.



Create a [Threading](#) operation.



Create a [Lathe Sequential](#) operation.



Create [Axial Machining Operations](#).

The following specific toolbar is accessed from the drop-down icon in the Auxiliary Operations toolbar.



It contains icons for creating and editing [Tool Change](#) operations as follows.



See [External tool](#) for more information about this resource



See [Internal tool](#) for more information about this resource



See [External Groove tool](#) for more information about this resource



See [Frontal Groove tool](#) for more information about this resource



See [Internal Groove tool](#) for more information about this resource



See [External Thread tool](#) for more information about this resource



See [Internal Thread tool](#) for more information about this resource.




Please note that the icon representing a Tool Change operation in the tree looks like this:



Specification Tree

Here is an example of a Process Product Resources (PPR) specification tree for NC Manufacturing products.



Process List is a plan that gives all the activities and machining operations required to transform a part from a rough to a finished state.

- **Part Operation** defines the manufacturing resources and the reference data.
- **Manufacturing Program** is the list of all of the operations and tool changes performed.

The example above shows that:

- Drilling.1 is complete and has not been computed
- Drilling.2 is complete but has been computed (by means of a replay)
- Drilling.3 does not have all of the necessary data (indicated by the exclamation mark symbol)
- Drilling.4 has been deactivated by the user (indicated by the brackets symbol)
- Drilling.5 has been modified and needs to be recomputed (indicated by the update symbol).

Product List gives all of the parts to machine as well as CATPart documents containing complementary geometry.

Resources List gives all of the resources such as machine or tools that can be used in the program.



Customizing

Tasks for customizing your NC Manufacturing environment are described in the *NC Manufacturing Infrastructure User's Guide*.

[NC Manufacturing Settings](#)

[Build a Tools Catalog](#)

[Access External Tools Catalogs](#)

[PP Word Syntaxes](#)

[NC Documentation](#)

Reference Information

Reference information that is specific to the Lathe Machining product can be found in this section.

Lathe Machining Operations
Cutter Compensation for Finish Operations
Changing the Output Point
Lathe Tool Assembly Considerations
Actual Stock Computation

Essential reference information on the following topics is provided in the *NC Manufacturing Infrastructure User's Guide*.

Associativity
NC Manufacturing Resources
NC Macros
PP Tables and PP Word Syntaxes
Feeds and Speeds
APT Formats
CLfile Formats

Lathe Machining Operations

The information in this section will help you create and manage the machining operations supported by the Lathe Machining product. These operations are:

- Roughing
- Recessing
- Grooving
- Profile Finishing
- Groove Finishing
- Threading
- Sequential Machining:
 - Go motion
 - Go InDirv motion
 - Go Delta motion
 - Follow motion.

Roughing Operations

The Roughing operation allow you to specify:

- Longitudinal, Face and Parallel Contour roughing modes
- external, internal or frontal machining according to the type of area to machine
- relimitation of the area to machine
- various approach and retract path types
- various lead-in and lift-off options with specific feedrates
- recess machining
- various contouring options with specific feedrates.

External and Internal turning and grooving tools may be used.

Geometry for Roughing

Part and Stock profiles are required.


The **End Limit** option allows you to specify a point, line or curve to relimit or extrapolate the selected part profile. The position of the end of machining is defined with respect to this element by one of the following settings: None / In / On / Out.

Orientation for Roughing


The following **Orientations** are proposed: Internal, External and Frontal (for Face and Parallel Contour Roughing only).

The selected Orientation defines the type of geometric relimitation to be done between the stock and part geometry in order to determine the area to machine. Selected part and stock profiles do not need to be joined (see the following figures).

External Roughing




Internal Roughing



Frontal Roughing

Frontal machining is proposed for face roughing. In that case, the minimum and maximum diameters of the area to machine are determined by the stock profile dimensions.


For example, in the following figure the area to machine is relimited by the spindle axis because the stock profile is also relimited by the spindle axis.



Location and Limits for Roughing

The following machining **Locations** are proposed:


- Front, the part is machined toward the head stock
- Back, the part is machined from the head stock.




Orientation and Location settings determine the way the program closes the area to machine using radial, axial, axial-radial or radial-axial relimitation.

The following options allow you to restrict the area to machine that is pre-defined by the stock and part. You may want to restrict this area due to the physical characteristics of the tool and the type of machining to be done.

Minimum Machining Radius



Maximum Machining Radius (for internal machining)



Note that Max Boring Depth is defined on the tool.

Axial Limit for Chuck Jaws (for external or frontal machining): Offset defined from the machining axis system.


Part and Stock Thicknesses for Roughing

- **Clearance on stock**, which is defined perpendicular to the stock profile.
- **Thickness on part**, which is defined perpendicular to the part profile.
- **Axial offset on part.**
- **Radial offset on part.**
- **End limit clearance:** distance with respect to the end element (only if end element is a line or a curve, and when In or Out is set for end element positioning).

Radial and axial offsets can be positive or negative with any absolute value. The thickness applied to the part profile is the resulting value of the normal thickness and the two offsets.


Thickness on part

In this example, a "virtual nose radius" is obtained by adding the specified thickness value to the real nose radius.




Axial offset on part

A "virtual part profile" is obtained by translating the part profile the specified offset value along the spindle axis direction.



Radial offset on part

A "virtual part profile" is obtained by translating the part profile the specified offset value perpendicular to the spindle axis direction.



Machining Strategy Parameters for Roughing

Path Definition for Roughing

- Machining tolerance

- **Max Depth of Cut**

This option is used to specify the maximum distance between passes.

It is replaced by Radial Depth of Cut and Axial Depth of Cut for Parallel Contour Roughing.

- **Leading and Trailing Safety Angles**

The insert geometry is taken into account to avoid collision by reducing the maximum slope on which the tool can machine. The Leading Safety Angle and Trailing Safety Angle allow you to further reduce this slope.

Note that Trailing Angle can be used only when Recess Machining is set.

Leading and trailing angles can also be defined on the tool to define the maximum slope on which the tool can machine. In this case, the angles that reduce the slope the most will be taken into account.

- **Part Contouring**

You can specify a contouring type for longitudinal and face roughing in order to clear the part profile by means of the following settings:

- No: no contouring
- Each path: profile following at each roughing pass
- Last path only: profile following at last roughing pass only.

- **Under Spindle Axis Machining**

For Face Roughing and Parallel Contour Roughing with Frontal machining, this option allows you to request machining under the spindle axis.

- **Machining Direction** (only for Parallel Contour and Face Roughing with Frontal machining)

You can specify the machining direction with respect to the spindle axis by means of the To/From Spindle Axis choice.


- **Recess Machining** (if Contouring Type is Each Pass or Last Path Only)

If you require recess machining, activate this checkbox.

When recess machining is active in Parallel Contour Roughing, the toolpath may not be collision free for some combinations of Axial and Radial Cut Depth.

The following options are proposed for recess machining:

- **Plunge Distance** and **Plunge Angle** (for longitudinal and face roughing)
Define the plunge vector before each new pass with respect to the cutting direction.



Example of recess with longitudinal external roughing. Note that Trailing angle is defined on the tool.


In the figure above the tool motion is as follows:

- approach in RAPID
- lead-in at the first recess pass and plunge approach for other passes
- plunge at plunge feedrate
- machine at machining feedrate
- contouring at contouring feedrate
- lift-off at last recess pass at lift-off feedrate.

Lead-in, Lift-off and Attack for Roughing


These options allow penetration into the workpiece at a reduced feedrate in order to prevent tool damage. Once the attack distance has been run through, the tool moves at machining feedrate.

- **Lead-in Distance**
Defined with respect to the cutting direction and the stock profile with a stock clearance. The tool is in rapid mode before this distance.
- **Lead-in Angle.**
If no lead-in angle is requested, lead-in path is parallel to the machining direction.
For Longitudinal and Face Roughing the Lead-in Angle can be applied as follows:
 - no angle applied to lead-in path
 - lead-in angle applied to each path
 - lead-in angle applied to last path only.
- **Attack Distance**
Defined with respect to the cutting direction and the stock profile with a stock clearance.



● **Lift-off Distance and Lift-off Angle**

Define the lift-off vector at the end of each new pass with respect to the cutting direction.



For Longitudinal or Face roughing, lift-off occurs:

- at the end of each pass when Contouring Type is set to None or Last Path Only.
- At the end of the last pass of the operation when the contouring type is set to Each Path. This prevents the tool from damaging the part when returning to the end point in RAPID mode.
- at the end of each pass that ends on the stock profile.

For Parallel Contour Roughing, lift-off occurs when the end of the pass has already been machined by a previous pass.

Feeds and Speeds for Roughing

- Speed unit can be set to:
 - Angular: spindle speed in revolutions per minute
 - Linear: constant cutting speed in units per minute

then you can give a Machining Speed value.


- Machining Feedrate in units per revolution
- Lead-in Feedrate which is applied during the lead-in and attack distance.
- Lift-off Feedrate
- Contouring Feedrate (if contouring type is Each Path or Last Path Only).
- Plunge Feedrate (for longitudinal and face roughing)
- Dwell setting indicates whether the tool dwell at the end of each path is to be set in seconds or a number of spindle revolutions.

Tool Compensation for Roughing

You can select a **tool compensation number** corresponding to the desired tool output point. Note that the usable compensation numbers are defined on the tool assembly linked to the machining operation. If you do not select a tool compensation number, the output point corresponding to type P9 will be used by default.


Approach and Retract Macros for Roughing

The following Approach and Retract macros are proposed: direct, axial-radial, radial-axial. The selected type (approach or retract) defines the tool motion before or after machining: the tool moves in rapid motion during the approach or retract.



Recessing Operation

The Recessing operation allows you to machine a recess by means of a One Way, Zig Zag or Parallel Contour tool motion.



You can specify:

- external, internal, frontal or inclined machining according to the type of area to machine
- various approach and retract path types
- various lead-in and lift-off options with specific feedrates
- part contouring
- tool output point change.

This operation supports all lathe tool types and inserts except threading tools.

Geometry for Recessing

Part and Stock profiles are required.

Orientation for Recessing

The following **Orientations** are proposed: internal, external, frontal and inclined.

The selected Orientation defines the type of geometric relimitation to be done between the stock and part geometry in order to determine the area to machine. For an inclined orientation you must specify the **Angle of Incline**.

Part and Stock Thicknesses for Recessing

- **Clearance on stock**, which is defined perpendicular to the stock profile
- **Thickness on part**, which is defined perpendicular to the part profile.
- **Axial offset on part**
- **Radial offset on part.**

Radial and axial offsets can be positive or negative with any absolute value. The thickness applied to the part profile is the resulting value of the normal thickness and the two offsets.

Machining Strategy Parameters for Recessing

Path Definition for Recessing

- **Recessing Mode: One Way, Zig Zag or Parallel Contour**

- **Max Depth of Cut**

This option is used to specify the maximum distance between passes.

- **Axial and Radial Depth of Cut**

These options are used to specify the maximum axial and radial distances between passes for Parallel Contour mode.

- **Machining tolerance**

- **Machining Direction**

For Zig Zag tool motion, you must specify a first cutting direction as follows:

- To or From Head Stock for Internal and External machining
- To or From Spindle for Frontal machining
- To Right or Left of Recess for Inclined machining

When a part profile has multiple recesses (that is, a non-convex profile along the cutting direction), only the first recess along the specified direction is machined.

- **Leading and Trailing Safety Angles** for One way and Parallel Contour modes

The insert geometry is taken into account to avoid collision by reducing the maximum slope on which the tool can machine. The Leading and Trailing Safety Angles allow you to further reduce this slope.

Note that leading and trailing angles can also be defined on the tool to define the maximum slope on which the tool can machine. In this case, the angles that reduce the slope the most will be taken into account.

- **Gouging Safety Angle** (for Zig Zag mode only)

Angles of the insert are taken into account to avoid collision by reducing the maximum slope on which the tool can machine. The Gouging Safety Angle allows you to further reduce this slope. Note that a gouging angle can also be defined on the tool to define the maximum slope on which the tool can machine. In this case, the angle that reduces the slope the most will be taken into account.


- **Under Spindle Axis Machining**

For Frontal or Inclined machining, this option allows you to request machining under the spindle axis.

- **Part Contouring**


You can specify if contouring is required by means of the proposed checkbox.

The part profile is followed at the end of recessing. This is done by machining down the sides of the recess in order to clear the profile.



Lead-in, Lift-off and Attack for Recessing

- **Lead-in Distance**
Defined with respect to the cutting direction and the stock profile with a stock clearance. The tool is in rapid mode before this distance.
- **Attack Distance**
Defined with respect to the cutting direction and the stock profile with a stock clearance.
- **Angle and Distance before Plunge**
Define the plunge vector before each new pass with respect to the cutting direction.
- **Lift-off Distance and Lift-off Angle**
Define the lift-off vector at the end of the last pass with respect to the cutting direction.



Example of one-way recessing. Note that Trailing angle is defined on the tool.

In the figure above the tool motion is as follows:

- approach in RAPID
- lead-in at the first recess pass and plunge approach for other passes
- plunge at plunge feedrate
- machine at machining feedrate
- contouring at contouring feedrate
- lift-off at last recess pass at lift-off feedrate.

Feeds and Speeds for Recessing

- Speed unit can be set to:
 - Angular: spindle speed in revolutions per minute
 - Linear: constant cutting speed in units per minute

then you can give a Machining Speed value.

- Machining Feedrate in units per revolution
- Lead-in Feedrate, which is applied during the lead-in and attack distance.
- Lift-off Feedrate
- Contouring Feedrate
- Plunge Feedrate
- Dwell setting indicates whether the tool dwell at the end of each path is to be set in seconds or a number of spindle revolutions.

Tool Compensation for Recessing

You can select a **tool compensation number** corresponding to the desired tool output point. Note that the usable compensation numbers are defined on the tool assembly linked to the machining operation. If you do not select a tool compensation number, the output point corresponding to type P9 will be used by default.

Note that the change of output point is managed automatically if you set the **Change Output Point** option.

If the output point is consistent with the flank of the recess to be machined, the output point is changed when the other flank of the recess is machined.

At the end of the operation, the output point is the same as it was at the start of the operation. See [Changing the Output Point](#) for more information.

Approach and Retract Macros for Recessing

The following Approach and Retract macros are proposed: direct, axial-radial, radial-axial. The selected type (approach or retract) defines the tool motion before or after machining: the tool moves in rapid motion during the approach or retract.

Grooving Operation

The Grooving operation allows you to machine a groove by a series of plunging cuts. You can specify:

- external, internal, frontal or inclined machining according to the type of area to machine
- various approach and retract path types
- various lead-in and lift-off options with specific feedrates
- various plunge locations
- tool output point change.

Grooving tools should be used.

Geometry for Grooving

Part and Stock profiles are required.

Orientation for Grooving

The following Orientations are proposed: internal, external, frontal and inclined. The selected Orientation defines the type of geometric relimitation to be done between the stock and part geometry in order to determine the area to machine. For an inclined orientation you must specify the **Angle of Incline**.

Part and Stock Thicknesses for Grooving

- **Clearance on stock**, which is defined perpendicular to the stock profile
- **Thickness on part**, which is defined perpendicular to the part profile.
- **Axial offset on part**
- **Radial offset on part.**

Radial and axial offsets can be positive or negative with any absolute value. The thickness applied to

the part profile is the resulting value of the normal thickness and the two offsets.

Machining Strategy Parameters for Grooving

Path Definition for Grooving

- **Max Depth of Cut**

This option is used to specify the maximum distance between plunges.

- **First Plunge**

You must specify a first plunge position according to the groove orientation by means of the following choice: Left/Down - Center - Right/Up - Automatic.

Automatic is only available for frontal machining. In this case, the position of the first plunge is deduced on the tool by reading the tool's minimum and maximum cutting diameters.

- **Next Plunges** (if First Plunge is set to Center).

You can specify the position of the plunges that follow the first plunge with respect to:

- the spindle axis by means of the To or From Spindle for frontal machining
- the head stock by means of the To or From Head Stock for internal or external machining
- the groove by means of Left or Right of Groove for Inclined machining.

- **Part Contouring**

You can specify if contouring is required by means of the proposed checkbox.

The part profile is followed at the end of grooving. This is done by machining down the sides of the groove in order to clear the profile.

- **Grooving by Level** mode

This option allows you to machine the groove in one or more level.

Multiple-levels mode is particularly useful when the groove is too deep to machine in one level. In this case Maximum grooving depth defines the maximum depth of each level. If it is greater than the Maximum Depth of Cut defined on the tool, the value on the tool is taken into account.

- **Under Spindle Axis Machining**

When grooving in frontal mode, this option allows you to request machining under the spindle axis.

- **Chip Break**

You can specify if chip clearing is to be done during machining by setting the check box. In this case you must specify Plunge, Retract and Clear distances.

- **Gouging Safety Angle**

Angles of the grooving insert are taken into account to avoid collision by reducing the maximum slope on which the tool can machine. The Gouging Safety Angle allows you to further reduce this slope.

Note that a gouging angle can also be defined on the tool to define the maximum slope on which the tool can machine. In this case, the angle that reduces the slope the most will be taken into account.

- **Machining Tolerance.**

Lead-in, Lift-off and Attack for Grooving

- **Lead-in Distance**

Defined with respect to the cutting direction and the stock profile with a stock clearance. The tool is in rapid mode before this distance.

- **Attack Distance**

Defined with respect to the cutting direction and the stock profile with a stock clearance.

These options allow penetration into the workpiece at a reduced feedrate in order to prevent tool damage. Once the attack distance has been run through, the tool moves at machining feedrate.

When tool motion between two passes is in contact with the part profile, in order to avoid collisions the corresponding feed is the lift-off feedrate and not rapid feedrate.

- **Lift-off Distance and Lift-off Angle**

Define the lift-off vector at the end of each new pass with respect to the cutting direction.

Feeds and Speeds for Grooving

- Speed unit can be set to:
 - Angular: spindle speed in revolutions per minute
 - Linear: constant cutting speed in units per minute
- then you can give a Machining Speed value.
- Contouring Feedrate
- Lead-in Feedrate, which is applied during lead-in and attack distances.
- Lift-off Feedrate
- First Plunge Feedrate and Next Plunges Feedrate
Different feedrates can be assigned to the first plunge and the following plunges.
- Dwell setting indicates whether the tool dwell at the end of a path or a plunge is to be set in seconds or a number of spindle revolutions.

Tool Compensation for Grooving

You can select a **tool compensation number** corresponding to the desired tool output point. Note that the usable compensation numbers are defined on the tool assembly linked to the machining operation. If you do not select a tool compensation number, the output point corresponding to type P9 will be used by default.

Note that the change of output point is managed automatically if you set the **Change Output Point** option.

If the output point is consistent with the flank of the groove to be machined, the output point is changed when the other flank of the groove is machined.

At the end of the operation, the output point is the same as it was at the start of the operation. See [Changing the Output Point](#) for more information.

Approach and Retract Macros for Grooving

The following Approach and Retract macros are proposed: direct, axial-radial, radial-axial. The selected type (approach or retract) defines the tool motion before or after machining: the tool moves in rapid motion during the approach or retract.

Profile Finishing Operation

The Profile Finishing operation allows you to finish a part profile. You can specify:

- the type of machining according to the profile of the area to machine (external, internal or frontal)


- relimitation of the profile by start and end elements
- various approach and retract path types
- linear and circular lead-in and lift-off options with specific feedrates
- recess machining
- various corner processing options
- cutter compensation.

External and Internal tools can be used.

Geometry for Profile Finishing

A Part profile is required.

- **Start Limit:** None / In / On / Out
This option allows you to specify a point, line or curve as the start element of the part profile. The position of the start of machining is also defined with respect to this element.
In / On / Out: allows you to specify the Go-Go type positioning of the tool with respect to the start element. The On option is always used for a point type start element.
If needed, the profile may be extrapolated to the start element.
- **End Limit:** None / In / On / Out
This option allows you to specify a point, line or curve as the end element of the part profile. The position of the end of machining is also defined with respect to this element.
In / On / Out: allows you to specify the Go-Go type positioning of the tool with respect to the end element.
If needed, the profile may be extrapolated to the end element.



Use of start and end elements for profile finishing. Profile is machined from start element. Profile is extrapolated up to end element. Direct approach and radial-axial retract.

Orientation and Location for Profile Finishing

- **Orientation:** Internal / External / Frontal

This option allows you to specify the type of machining according to the location of the area to machine on the part.


- **Location:**

- Front, the profile is machined toward the head stock
- Back, the profile is machined from the head stock.

Corner Processing for Profile Finishing

The following options allow you to define how corners of the profile are to be machined:

- None: no corners are to be machined along the profile
- Chamfer: only 90 degree corners of the profile are chamfered
- Rounded: all corners of the profile are rounded.



Corner processing options are also available to define how the entry and exit corners are to be machined. Entry and exit corners are defined by either a chamfer length, or a corner radius and corner angle.

Part Thicknesses for Profile Finishing

- **Thickness on part**, which is defined perpendicular to the part profile.

- **Axial offset on part.**
- **Radial offset on part.**
- **Start limit clearance:** distance with respect to the start element (only if start element is a line or a curve, and when In or Out is set for start element positioning).
- **End limit clearance:** distance with respect to the end element (only if end element is a line or a curve, and when In or Out is set for end element positioning).

Radial and axial offsets can be positive or negative with any absolute value. The thickness applied to the part profile is the resulting value of the normal thickness and the two offsets.

In addition to these global thickness and offsets, local thicknesses and offsets can be applied to segments, curves and arcs of the part profile.



Machining Strategy Parameters for Profile Finishing

Path Definition for Profile Finishing

- **Machining Direction:** To or From Spindle
This option is only available for frontal machining for specifying the machining direction with respect to the spindle axis.

If start and end elements are defined that are in conflict with the machining direction, then these elements will be reversed automatically.

- **Contouring for Outside Corners:** Angular / Circular
Allows you to define whether angular or circular contouring is to be applied to corners of the profile (only if corner processing is set to Rounded or Chamfer).



- **Under Spindle Axis Machining**
When finishing in frontal mode, this option allows you to request machining under the spindle axis.

- **Recess Machining**

When this option is set, the trailing safety angle option is available.

- **Leading and Trailing Safety Angles**

The insert geometry is taken into account to avoid collision by reducing the maximum slope on which the tool can machine. The Leading Safety Angle and Trailing Safety Angle allow you to further reduce this slope.

Note that leading and trailing angles can also be defined on the tool to define the maximum slope on which the tool can machine. In this case, the angles that reduce the slope the most will be taken into account.


- **Machining Tolerance** for following the profile.

Lead-in and Lift-off for Profile Finishing

- **Lead-in type:** Linear / Circular

Defines the type of lead-in onto the profile at lead-in feedrate

- Linear: lead-in up to the point where profile machining starts is defined by means of the **lead-in distance** and **lead-in angle** options.
- Circular: lead-in is circular and tangent to the point where profile machining starts. It is defined by means of the **lead-in radius** and **lead-in angle** options.




Linear lead-in and circular lift-off (profile finishing)

- **Lift-off type:** Linear / Circular.

Defines the type of lift-off from the profile at lift-off feedrate

- Linear: lift-off from the point where profile machining ends is defined by means of the **lift-off distance** and **lift-off angle** options.
- Circular: lift-off is circular and tangent from the point where profile machining ends. It is defined by means of the **lift-off radius** and **lift-off angle** options.

In the example below, the round tool is tangent **In** start element plus clearance at start of profiling. Round tool is tangent **Out** end element plus clearance at end of profiling.



Feeds and Speeds for Profile Finishing

- Speed unit can be set to:
 - Angular: spindle speed in revolutions per minute
 - Linear: constant cutting speed in units per minute

then you can give a Machining Speed value.

- Machining Feedrate in units per revolution
- Chamfering Feedrate for machining chamfers or corners (in units per revolution)
- Lift-off Feedrate in units per revolution
- Lead-in Feedrate in units per revolution.

In addition to these global feedrates, local feedrates can be applied to segments, curves and arcs of the part profile.

Tool Compensation for Profile Finishing

You can select a **tool compensation number** corresponding to the desired tool output point. Note that the usable compensation numbers are defined on the tool assembly linked to the machining operation. If you do not select a tool compensation number, the output point corresponding to type P9 will be used by default.

CUTCOM (Cutter Compensation): None / On / Reverse.

If this option is set to On or Reverse, the NC output will include CUTCOM instructions in approach and retract paths for cutter compensation.

- On: CUTCOM/RIGHT instruction generated if tool is to the right of the toolpath and CUTCOM/LEFT if tool is to the left of the toolpath.
- Reverse: CUTCOM/RIGHT instruction generated if tool is to the left of the toolpath and CUTCOM/LEFT if tool is to the right of the toolpath.

See [Cutter Compensation with Finish Operations](#) for more information.

Approach and Retract Macros for Profile Finishing

The following Approach and Retract macros are proposed: direct, axial-radial, radial-axial. The selected type (approach or retract) defines the tool motion before or after machining: the tool moves in rapid motion during the approach or retract.

Groove Finishing Operation

The Groove Finishing operation allows you to finish a groove by means of downward profile following. You can specify:

- the type of machining according to the groove profile to be machined (external, internal, frontal or inclined)
- relimitation of the profile by start and end elements
- various approach and retract path types
- linear and circular lead-in and lift-off options with specific feedrates
- various corner processing options with specific feedrates
- local feedrates for individual elements of the machined profile
- tool output point change
- cutter compensation.

Grooving tools or round inserts should be used.

Geometry

The Part profile is required.

- **Start Limit:** None / In / On / Out
This option allows you to specify a point, line or curve as the start element of the groove finish profile. The position of the start of machining is also defined with respect to this element.
 - **In / On / Out:** allows you to specify the Go-Go type positioning of the tool with respect to the start element. The On option is always used for a point type start element.

If needed, the groove finish profile may be extrapolated to the start element.

- **End Limit:** None / In / On / Out
This option allows you to specify a point, line or curve as the end element of the groove finish profile. The position of the end of machining is also defined with respect to this element.
 - **In / On / Out:** allows you to specify the Go-Go type positioning of the tool with respect to the end element. The On option is always used for a point type start element.

If needed, the groove finish profile may be extrapolated to the end element.

Orientation for Groove Finishing

- **Orientation:** Internal / External / Frontal / Inclined
This option allows you to define the orientation of the groove to be machined.
For an inclined orientation you must specify the **Angle of Incline**.

Corner Processing for Groove Finishing

The following options allow you to define how corners of the profile are to be machined:

- Follow profile: no corners are to be machined along the profile
- Chamfer: only 90 degree corners of the profile are chamfered
- Rounded: all corners of the profile are rounded.

Corner processing is proposed for **Entry, Exit** and **Other corners**.

- Chamfer Length if Other corner processing mode is Chamfer.
- Corner Radius if Other corner processing mode is Rounded.
- Entry Corner Chamfer Length on first flank of groove when Entry corner processing mode is Chamfer
- Entry Corner Radius on first flank of groove when Entry corner processing mode is Corner
- Entry Corner Angle on first flank of groove when Entry corner processing mode is Corner
- Exit Corner Chamfer Length on last flank of groove when Exit corner processing mode is Chamfer
- Exit Corner Radius on last flank of groove when Exit corner processing mode is Corner
- Exit Corner Angle on last flank of groove when Exit corner processing mode is Corner.

Part Thicknesses for Groove Finishing

- **Thickness on Part**, which is defined perpendicular to the part profile.
- **Axial Offset on Part**
- **Radial Offset on Part**.
- **Start Limit Clearance**: distance with respect to the start element (only if start element is a line or a curve, and when In or Out is set for start element positioning).
- **End Limit Clearance**: distance with respect to the end element (only if end element is a line or a curve, and when In or Out is set for end element positioning).

Radial and axial offsets can be positive or negative with any absolute value. The thickness applied to the part profile is the resulting value of the normal thickness and the two offsets. In addition to these global thickness and offsets, local thicknesses and offsets can be applied to segments, curves and arcs of the part profile.

Machining Strategy Parameters for Groove Finishing

Path Definition for Groove Finishing

- **Machining Direction**

You can specify the machining direction by means of:

- To or From Head for Internal and External machining
- To or From Spindle for Frontal machining
- To Right or Left of Groove for Inclined machining

If start and end elements are defined that are in conflict with the machining direction, then these elements will be reversed automatically.

- **Clearance**: this value defines the clearance to be applied to the next flank after the first machined flank. The bottom of the groove will be machined up to the position defined by this clearance value.
- Tool **Overlap** Distance on Groove Bottom.

- **Under Spindle Axis Machining**

When finishing in frontal mode, this option allows you to request machining under the spindle axis.

- **Contouring for Outside Corners: Angular / Circular**

Allows you to define whether an angle or circle contouring mode is to be applied to corners of the groove profile (only if corner processing is set to None or Chamfer).

- **Machining Tolerance** for following the groove finish profile.


Lead-in for Groove Finishing

- **First Flank Lead-in: Linear / Circular**

Defines the type of lead-in at lead-in feedrate on the first flank of the groove.

- Linear: lead-in up to the point where first flank machining starts is defined by means of the **first lead-in distance** and **first lead-in angle** options.
- Circular: lead-in is circular and tangent to the point where first flank machining starts. It is defined by means of the **first lead-in radius** and **first lead-in angle** options.

The example below shows Linear lead-in and Circular lift-off for groove finishing.



- **Last Flank Lead-in: Linear / Circular**

Defines the type of lead-in at lead-in feedrate on the last flank of the groove.

- Linear: lead-in up to the point where last flank machining starts is defined by means of the **last lead-in distance** and **last lead-in angle** options.
- Circular: lead-in is circular and tangent to the point where last flank machining starts. It is defined by means of the **last lead-in radius** and **last lead-in angle** options.

- **Other Flank Lead-in: Linear / Circular**

For a groove that has multiple recesses, this option defines the type of lead-in required to machine flanks other than the first and last flanks.

- **Other Lead-in Distance** on other flanks of the groove when other flank lead-in type is Linear
- **Other Lead-in Angle** on other flanks of the groove when other flank lead-in type is Linear or Circular
- **Other Lead-in Radius** on other flanks of the groove when other flank lead-in type is Circular.

Lift-off for Groove Finishing

- **Lift-off Type: Linear / Circular**

Defines the type of lift-off from the groove at lift-off feedrate.

- **Lift-off Distance** when lift-off type is Linear.
- **Lift-off Angle** when lift-off type is Linear or Circular.
- **Lift-off Radius** when lift-off type is Circular.

Feeds and Speeds for Groove Finishing

- Speed unit can be set to:

- Angular: spindle speed in revolutions per minute
- Linear: constant cutting speed in units per minute

then you can give a Machining Speed value.

- **Machining Feedrate** in units per revolution
- **Chamfering Feedrate** for machining chamfers or corners (in units per revolution)
- **Lift-off Feedrate** in units per revolution
- **Lead-in Feedrate** in units per revolution.

In addition to these global feedrates, local feedrates can be applied to segments, curves and arcs of the part profile.

Tool Compensation for Groove Finishing

You can select a **tool compensation number** corresponding to the desired tool output point. Note that the usable compensation numbers are defined on the tool assembly linked to the machining operation. If you do not select a tool compensation number, the output point corresponding to type P9 will be used by default.

CUTCOM (Cutter Compensation): None / On / Reverse

If this option is set to On or Reverse, the NC output will include CUTCOM instructions in approach and

retract paths for cutter compensation.

- On: CUTCOM/RIGHT instruction generated if tool is to the right of the toolpath and CUTCOM/LEFT if tool is to the left of the toolpath.
- Reverse: CUTCOM/RIGHT instruction generated if tool is to the left of the toolpath and CUTCOM/LEFT if tool is to the right of the toolpath.

See [Cutter Compensation with Finish Operations](#) for more information.

Note that the change of output point is managed automatically if you have set the **Change Output Point** option. If the output point is consistent with the flank of the groove to be machined, the output point is changed when the other flank of the groove is machined. At the end of the operation, the output point is the same as it was at the start of the operation. See [Changing the Output Point](#) for more information.

Approach and Retract Macros for Groove Finishing

The following Approach and Retract macros are proposed: direct, axial-radial, radial-axial. The selected type (approach or retract) defines the tool motion before or after machining: the tool moves in rapid motion during the approach or retract.

Threading

The Threading operation allows you to specify:

- the type of machining according to the required thread (external or internal)
- relimitation of the profile by start and end elements
- thread machining options
- various approach and retract types
- PP Word syntaxes.

External and Internal threading tools can be used.

Geometry for Threading

A Part profile is required.

- **End Limit:** None / In / On / Out
This option allows you to specify a point, line or curve as the end element of the profile to be machined. The position of the end of machining is also defined with respect to this element.
In / On / Out: allows you to specify the Go-Go type positioning of the tool with respect to the end element. The On option is always used for a point type end element.
If needed, the profile may be extrapolated to the end element.
- **End Limit Clearance:** distance with respect to the end element (only if end element is a line or a curve, and when In or Out is set for end element positioning).
- **Start Limit:** None / In / On / Out
This option allows you to specify a point, line or curve as the start element of the profile to be machined. The position of the start of machining is also defined with respect to this element.
In / On / Out: allows you to specify the Go-Go type positioning of the tool with respect to the start element. The On option is always used for a point type end element.
If needed, the profile may be extrapolated to the start element.

- **Start Limit Clearance:** distance with respect to the start element (only if start element is a line or a curve, and when In or Out is set for start element positioning).

Orientation and Location for Threading

- **Orientation:** Internal / External
This option allows you to specify the type of machining according to the location of the area to machine on the part.
- **Location:** Front / Back
 - Front, the profile is machined toward the head stock
 - Back, the profile is machined from the head stock.

Threads

- **Thread profile:** ISO / Trapezoidal / UNC / Gas / Other
Other allows defining a specific thread profile.
- **Thread unit:** Pitch / Threads per Inch
You must specify the thread type when the Thread profile is Other. Thread is automatically set to Pitch for the ISO and Trapezoidal types and set to Threads per Inch for UNC and Gas.
- **Nominal diameter**
This value must be given when Thread type is internal and Thread profile is Other.
- **Thread length**
This value must be given when the Start or End relimiting element is set to Profile End.
- **Thread pitch**
This value must be given when the Thread type is set to Pitch or the Thread profile is ISO or Trapezoidal.
- **Threads/inch**
This value must be given when the Thread type is set to Thread per inch or when the Thread profile is UNC or Gas.
- **Thread depth**
This value must be given when the Thread profile is Other.
- **Number of threads**
When greater than 1, this value allows you to specify whether a multi-start thread is to be machined.

Machining Strategy Parameters for Threading

Machining Options for Threading

- **Threading type.** You must choose the desired threading type:
 - Constant depth of cut
 - Constant section of cut
- Maximum **Depth of cut** when Threading type is set to Constant depth of cut
- **Number of passes** when Threading type is set to Constant section of cut.
When the number of passes is defined, the Section of cut value is automatically set.
- **Machining spindle speed**

- **Thread Penetration type:**

- Straight
- Oblique
- Alternate.

Penetration angle must be specified for Oblique or Alternate entry types.

Path Computation options for Threading

- **Clearance on crest diameter**
- **Lead-in Distance**
- **Lift-off Distance** and **Lift-off Angle**.

First and Last Passes options for Threading

- Manage penetration on first passes by means of the **First passes** check box. This option is available when Threading type is set to Constant section of cut. When activated, you must specify values for:
 - **Number of first passes**
 - **First section rate**.

When these two values are specified, the Section of cut for first passes value is automatically set.

- Manage penetration on the last passes by means of the **Last passes** check box. When activated, you must specify:
 - **Number of last passes**
 - **Depth of cut for last passes**.
- Manage the spring passes by means of the **Spring passes** check box. When activated, you must specify a **Number of spring passes**.

CYCLE or GOTO Output Syntaxes

If you want to generate CYCLE statements, you must select the **Output CYCLE syntax** checkbox in the Options tab and set the **Syntax Used** option to Yes in the NC Output generation dialog box. Otherwise, GOTO statements will be generated.

The parameters available for PP word syntaxes for this type of operation are described in the [NC_LATHE_THREADING](#) section of the [Manufacturing Infrastructure User's Guide](#).

Tool Compensation for Threading

You can select a **tool compensation number** corresponding to the desired tool output point. Note that the usable compensation numbers are defined on the tool assembly linked to the machining operation. If you do not select a tool compensation number, the output point corresponding to type P9 will be used by default.

Note that the change of output point is managed automatically if you set the **Change Output Point** option for Trapezoidal or Other Thread profile.

Approach and Retract Macros for Threading

The following Approach and Retract macros are proposed: direct, axial-radial, radial-axial. The selected type (approach or retract) defines the tool motion before or after machining: the tool moves in rapid motion during the approach or retract.

Sequential Machining

You can create a sequence of basic Go, Go InDirv, Go Delta, and Follow tool motions in a single Sequential Machining operation. PP words can be inserted in the sequence of tool motions.

When you select the Tool motion management icon a panel is displayed listing any previously created tool motions and PP words. You can create or edit tool motions and PP words.

If there are no previously created tool motions listed in the panel, you are prompted to create a start position. This start position must be a Go motion that uses either a point or two different check elements.

When defining a tool motion, the corresponding new tool position is displayed according to all the options that were selected for creating this motion.

Geometry Selection

You can select point / line / curve / edge elements as follows:

Point / line and curve elements must belong to the plane that is defined by the machine spindle axis and radial axis.

Edge elements must be coaxial with the machine spindle axis.

Go Motion

In Go motion, the program positions the tool with respect to one or two check elements.

When only one check element is selected, the tool is projected onto the check element.

When two check elements are selected, the tool is positioned with respect to the two check elements.

The tool is positioned with respect to each check element depending on the TO-ON-PAST mode.

TO: the tool nose is positioned tangent to the near side of the selected element with a possible thickness or offset.

ON: the tool nose is positioned on the selected element, with a possible axial or radial offset (normal thickness, collision avoidance and safety angles are not applicable).

PAST: the tool nose is positioned tangent to the far side of the selected element with a possible thickness or offset.

The first check element can be point, line, curve, or edge type elements.

If it is a point, no second check element can be selected. Otherwise, the second check element can be line, curve or edge type elements.

The following options are available when defining a Go motion:

- Control over geometric extrapolation of each check curve.
- Normal thickness, and axial and radial offset with respect to each check element.
- Feedrate and spindle speed.
- Collision avoidance for each check element when the tool is positioned in TO or PAST mode.
- Left and right safety angles when collision avoidance is used.
- Machining tolerance
- Tool compensation
- Guiding Point, if a square or grooving insert is used.

Note that the positioning mode (TO, ON, PAST), clearance, thickness and offset are not applicable when the tool is positioned on a point.

Go InDirv Motion

In Go InDirv (Go in Direction Vector) motion, the tool moves in a given direction up to the selected check curve.

The tool is positioned with respect to the selected element depending on the TO-ON-PAST mode.

TO: the tool nose is positioned tangent to the near side of the selected element with a possible thickness or offset.

ON: the tool nose is positioned on the selected element, with a possible axial or radial offset (normal thickness, collision avoidance and safety angles are not applicable).

PAST: the tool nose is positioned tangent to the far side of the selected element with a possible thickness or offset.

The selected check curve can be edge, line and curve type elements.

The following options are available when defining a Go InDirv motion:

- Drive element type: line or angle.
- Angle of drive, if drive element type is angle.
- Drive direction: Same or Inverted.
This is useful in the particular case when two positions are reachable.
- Control over geometric extrapolation of check curve.
- Normal thickness, and axial and radial offset with respect to the check element.
- Feedrate and spindle speed.
- Collision avoidance when the tool is positioned in TO or PAST mode.
- Left and right safety angles when collision avoidance is used.
- Machining tolerance
- Tool compensation
- Guiding Point, if a square or grooving insert is used.

Go Delta Motion

In Go Delta motion, the tool move is based on the current position of the tool. The TO-ON-PAST mode is not proposed.

The following options are available when defining a Go Delta motion:

- Delta check mode:
 - Distance between two points (two points are to be selected)
 - Line and distance (line and distance are to be selected)
 - Angle and distance (angle and distance are to be given)
 - Axial and radial (axial and radial offsets are to be given)
- Feedrate and spindle speed.
- Machining tolerance
- Tool compensation.

Follow Motion

In Follow motion, the tool follows a drive element up to a check element. The check element is to be selected in the Follow motion and can be an edge, line, a curve or a point.

The drive element is a curve on which the tool is positioned by a preceding motion. Therefore, the preceding motion must be a Go, Go InDirv or Follow motion. A Go to a point or a Go Delta cannot precede a Follow motion.

If the preceding motion is a Go motion, the first selected check curve is used as drive curve for the Follow motion.

If the preceding motion is a Go InDirv motion, the selected check curve is used as drive curve for the Follow motion.

If the preceding motion is a Follow motion, the check element of the preceding Follow motion is used as drive curve when this check element is not a point and the Change Drive option of the preceding Follow motion is set. Otherwise, both consecutive Follow motions share the same drive curve.

Note that:

- the thickness and offsets applied to follow the drive element are also defined on the same preceding motion. When the drive and check curves are tangent, any thickness and offset values on the check curve should be the same on the tangent drive curve.
- the collision avoidance and the control over geometry extrapolation on drive curve are also defined on the same preceding motion.

The tool will follow the drive element up to the check element. The final tool position will be determined by the TO-ON-PAST mode:

TO: tool nose tangent to the drive element and before the check element with a possible thickness or offset.

ON: tool nose tangent to the drive element and on the check element, with a possible axial or radial offset (normal thickness is not applicable).

PAST: tool nose tangent to the drive element and after the check element with a possible thickness or offset.

The following options are available when defining a Follow motion:

- Drive direction: Same or Inverted.
This is useful in the particular case when two positions are reachable.
- Control over geometric extrapolation of check curve.
- Normal thickness, and axial and radial offset with respect to the check element.
- Feedrate and spindle speed.
- Collision avoidance when the tool is positioned in TO or PAST mode.

- Left and right safety angles when collision avoidance is used.
- Machining tolerance
- Tool compensation
- Guiding Point, if a square or grooving insert is used.

Control over Geometric Extrapolation of Check Curve

When check limit mode is set to Extended, a virtual tangent element is added to each extremity of the check element before it is actually taken into account as a check element.

Therefore, if there is no intersection between the drive and check elements, the final tool position may be located at the intersection of the drive curve and a tangent of the check element.

When check limit mode is set to Actual, no virtual tangent element is added.

Therefore, the final tool position is located on the check element.

Furthermore, please note that control over geometric extrapolation is not controlled in the Follow motion but on the preceding motion that positions the tool on the drive element.

Note that collision avoidance is taken into account for positioning in ON mode, and that left and right safety angles are only considered in collision avoidance mode.



Cutter Compensation with Finish Operations

The **Cutter Compensation: None / On / Reverse** option is proposed for finish operations. If this option is set to On or Reverse, the NC output will include CUTCOM instructions in the APT or cfile output for cutter compensation (CUTCOM/RIGHT, CUTCOM/LEFT, CUTCOM/OFF).


- **On:** CUTCOM/RIGHT instruction generated if tool is to the right of the toolpath and CUTCOM/LEFT if tool is to the left of the toolpath
- **Reverse:** CUTCOM/RIGHT instruction generated if tool is to the left of the toolpath and CUTCOM/LEFT if tool is to the right of the toolpath.

Otherwise, if the option is set to **None**, no CUTCOM instruction will be included in the NC data output.

A CUTCOM instruction is always generated before a linear trajectory in order to be active on that displacement:

- for a tool approach, the instruction CUTCOM/RIGHT or CUTCOM/LEFT is generated at latest in the approach phase of the trajectory, before the lead-in and on a linear trajectory
- for a tool retract, the instruction CUTCOM/OFF is generated at earliest in the retract phase of the trajectory, before a linear trajectory or the last point of the operation.

The figure below illustrates a Profile Finishing operation that has circular lead-in and linear lift-off.



If the cutter compensation is set to ON, the CUTCOM instructions are generated as follows:

- CUTCOM/RIGHT is generated at point 1, before the tool motion to point 2.
Note that if lead-in was linear, CUTCOM/RIGHT would be generated at point 2, before the tool motion to point 3.
- CUTCOM/OFF is generated at point 4, before the tool motion to point 5.
Note that if lift-off was circular CUTCOM/OFF would be generated at point 5, before the linear retract motion.

How to Use Cutter Compensation

The computed toolpath corresponds to the trajectory followed by the output point of the tool used in the Part Operation. You should set Cutter Compensation to On in the following cases:

- the cutter radius of the actual tool used for machining is greater than the radius of the programmed tool and a positive compensation value is entered at the NC machine
- the cutter radius of the actual tool used for machining is less than the radius of the programmed tool and a negative compensation value is entered at the NC machine.

You should set Cutter Compensation to Reverse in the following cases:

- the cutter radius of the actual tool used for machining is less than the radius of the programmed tool and a positive compensation value is entered at the NC machine
- the cutter radius of the actual tool used for machining is greater than the radius of the programmed tool and a negative compensation value is entered at the NC machine.

Some Recommendations


In general you should program with tools whose cutter radius is greater than those that will actually be used on the machine. This will help you anticipate tool/part collisions that may arise when cutter compensation is used. If negative compensation values are allowed on the machine, set Cutter Compensation to On. If negative compensation values are not allowed on the machine set Cutter Compensation to:

- On, if the tool actually used has a greater cutter radius than the programmed tool
- Reverse, if the tool actually used has a smaller cutter radius than the programmed tool.

The figure below illustrates cutter compensation for profile finishing.

CATIA Tool Nose Radius

CATIA Tool Path



Changing the Output Point

An option for changing the tool output point is available for:

- Recessing, Grooving and Groove Finishing operations using grooving tools or inserts
- certain Threading operations using threading tools or inserts.

When the **Change Output Point** option is set the tool output point will be changed automatically during the operation according to the profile geometry to be machined.


For Grooving and Groove Finishing operations, tool output point changes are made out of the profile.

For Recessing operations, tool output point changes are made before each tool motion involving machining (that is, after each plunge). However, changes are only done:

- if machining is consistent with the selected tool output point
- if another output point is defined on the tool so that the tool output point change can be made.

Otherwise, the tool output point will not be changed.

The following figure illustrates tool output point changes in a Groove Finishing operation that uses a grooving tool. In this example, at the start of operation the tool output point is P9.



If the first flank to machine is flank 1, the tool motion is as follows:

- approach and lead-in motion to flank 1
- machine down flank 1
- lift-off from part profile
- tool output point change: tool output point is P9R
- approach and lead-in motion to flank 2
- machine down flank 2
- lift-off to Exit Point
- tool output point change: tool output point is P9 (as at start of operation).

If the first flank to machine was flank 2, the tool motion would be as follows:


- tool output point change: tool output point is P9R
- approach and lead-in motion to flank 2

- machine down flank 2
- lift-off from part profile
- tool output point change: tool output point is P9 and the guiding point is LEFT
- approach and lead-in motion to flank 1
- machine down flank 1
- lift-off to Exit Point.

If P9 is the tool output point and if the output point P9R is defined on the tool, the output point change is only done for grooving tools.

The tool output point at the end of operation is the same as at the start of operation.

The figure below illustrates a Recessing operation when a round insert is used. The tool output point changes during an operation only if the output point at the start of operation is P2, P3 or P9 for a frontal recess or P3, P4 or P9 for an external recess.



The tool output point is dependent on the machine axis system.



Lathe Tool Assembly Conventions


General Comments

The Machining Axis is always a direct axis system. For example, ZX defines a direct axis system with Z as the Spindle Axis and X as the radial axis.

Selected geometry (for example, Finish Profile) can be selected either in X+ or X- :

- the system will figure out whether machining is in X+ or X- based on Insert-Holder orientation (as defined using Set-Up Angle)
- depending on the options of a Machining Operation, several possibilities might exist, (for example, Frontal machining). User option is then available (X+/X-) to specify what the system should do.

The Output Point definition is considered according to the X+/Z+ quadrant.




Examples below deal with Horizontal Lathe Machine Tool.


Insert Holder

Different settings of the Setup Angle, Invert Tool and Hand Style parameters result in different configurations for positioning the tool .


Left Tool: Insert is visible and points to left:



Inverted Left Tool :



Right Tool: Insert is visible and points to right:




Inverted Right Tool:



Output Point


In the following figure reference is made according to the Spindle/Radial Axis (Z/X)




Spindle Rotary Direction

With a Horizontal Lathe Machine Tool the convention for spindle rotary direction defined in the Machine Editor dialog box is as follows:
Looking into Z direction, Chuck & Jaws at your back.


Clockwise



Counterclockwise




The following represent common settings:




180° Setup Angle

When Setup angle is set to 180°, machining takes places in X- as system detects that this is what the tool can machine (geometry can be selected in X+ or X-).




Direct Machining Axis

As the Machining Axis is always considered as being direct, the two situations below are the same (this corresponds to a rotation around the spindle axis).



Summary

The following figures summarize conditions for lathe tool assemblies.




The figure below shows other settings for different output points.

- « Right » Tool
- Set-Up Angle = 180°
- Inversion = YES

- « Left » Tool
- Set-Up Angle = 180°
- Inversion = YES

- « Left » Tool
- Set-Up Angle = 180°
- Inversion = NO

- « Right » Tool
- Set-Up Angle = 180°
- Inversion = NO



- « Right » Tool
- Set-Up Angle = -90° ; Inversion = NO

- « Left » Tool ; Set-Up Angle = -90°
- Inversion = YES

- « Right » Tool
- Set-Up Angle = -90° ; Inversion = NO

- « Right » Tool
- Set-Up Angle = 0°
- Inversion = NO

- « Right » Tool
- Set-Up Angle = 0°
- Inversion = YES

- « Left » Tool
- Set-Up Angle = 0° ; Inversion = YES

- « Left » Tool
- Set-Up Angle = 0° ; Inversion = NO



How to Use Actual Stock Computation

When you want to select the stock and part of a new machining operation, you can create the Actual Stock from the current operation.


This is done using the **Actual Stock Computation** command in the geometry tab page. The Actual Stock computation can be launched before the part or stock selection to create a sketch putting in emphasis the remaining material on the part. The computation takes into account all complete operations before the one which is edited.

The computation of the Actual Stock uses the "Stock for simulation", that you have to select in the Part Operation panel. The primitives of the material removed by each lathe operation will be subtracted from this stock.


The result of the computation is a sketch which contains the view of the remaining material in the working plane.

The first step before using Actual Stock Computation is to select a stock for simulation.


Double click on the Part Operation icon and select the Stock icon in the Part Operation dialog box.



Select the stock, then double click on the background to leave selection mode.




The Part Operation panel shows the name of the selected stock. In order to use Actual Stock Computation, you must select a lathe machine. The spindle and radial machine must be initialized correctly.




The second step is to initialize the In-Process Model body (IPM body) in the Part Operation panel.

The actual stock contour will be computed inside this body. Select a Part linked to your Product (or use "Insert a New Part" in the Assembly workbench on your existing product).

Double click on the part to enter the Part Design workbench and use the Insert > Body command to create a new body in your part. In this sample, call it "IPM_BODY".



The created "IPM_BODY" body will be put in "No Show" mode after the Actual Stock computation. So do not use an existing body otherwise your existing geometry will be in the No Show layer after the computation.



To summarize:

The setup for the computation, we need to define in Part Operation panel:

- a Lathe Machine with its spindle and radial axis initialized
- a Stock for simulation (solid) selected in the Part Operation panel
- an In Process Model body created inside an existing or newly created Part.

The operations taken into account by the Actual Stock computation are:


- Lathe Operations:
 - Roughing
 - Grooving
 - Recessing
 - Profile Finishing
 - Groove Finishing.
- All Drilling operations using a "fixed" Tool Assembly are taken into account. For this, select the Assembly tab page and click on More. In the Technology tab page the parameter "Power" must be set to "Fixed".

Lathe Threading operations are not taken into account for Actual Stock computation.

Example of Actual Stock Computation


The following figure illustrates the launching of the Actual Stock computation after a Drilling (with fixed Tool

assembly) and a Roughing operation. Here is the tool path of the roughing operation:



If you want to create another Roughing operation after the first one, click "Actual Stock computation" in the new Roughing operation's Geometry tab page.

The following figure shows the result of the computation. The Actual Stock has been created in blue. It is inside a sketch whose name is the name of the last machining operation taken into account for the computation: Roughing.1 plus the item StockSketch and the time of the computation. You can see that the Actual Stock sketch has been created in a body with the same name, just under the "IPM body". The "IPM body" is now in No Show mode.



You can now select elements of the Actual Stock sketch as new Part or new Stock item of the Roughing.2 operation.

To create the Actual Stock, some primitives are created inside the IPM body. Once the Actual Stock sketch is created, the Actual Stock sketch is no longer linked to them. If you use the Actual Stock computation again, the existing primitives will speed up the computation (they will be used if the operation they are linked with have not been modified since the first call to Actual Stock, otherwise they will be modified). This command will not remove the Actual Stock sketches or the IPM body.

To manage different Actual Stock sketches, you can change the color of each sketch by modifying the graphic property of the sketch.

If you have finished your Part Operation, you can remove these primitives by using the Remove IPM primitives contextual command on the Manufacturing Program. This command will remove each primitive of the IPM body linked to the operation inside the program.



Glossary

A

approach macro Motion defined for approaching the operation start point

auxiliary command A control function such as tool change or machine table rotation. These commands may be interpreted by a specific post-processor.

axial machining operation Operation in which machining is done along a single axis and is mainly intended for hole making (drilling, counter boring, and so on).

D

DPM Digital Process for Manufacturing.

E

extension type Defines the end type of a hole as being through hole or blind.

F

feedrate Rate at which a cutter advances into a work piece. Measured in linear or angular units (mm/min or mm/rev, for example).

fixture Elements used to secure or support the workpiece on a machine.

G

gouge Area where the tool has removed too much material from the workpiece.

M

machine rotation An auxiliary command in the program that corresponds to a rotation of the machine table.

machining axis system Reference axis system in which coordinates of points of the tool path are given.

machining operation Contains all the necessary information for machining a part of the workpiece using a single tool.

machining tolerance The maximum allowed difference between the theoretical and computed tool path.

manufacturing process Defines the sequence of [part operations](#) necessary for the complete manufacture of a part.

manufacturing program Describes the processing order of the NC entities that are taken into account for tool path computation: [machining operations](#), [auxiliary commands](#) and [PP instructions](#).

O

offset Specifies a virtual displacement of a reference geometric element in an operation (such as the offset on the bottom plane of a pocket, for example). Compare with [thickness](#).

one way Machining in which motion is always done in the same direction. Compare with [zig zag](#).

P

part operation Links all the operations necessary for machining a part based on a unique part registration on a machine. The part operation links these operations with the associated fixture and set-up entities.

PP instruction Instructions that control certain functions that are auxiliary to the tool-part relationship. They may be interpreted by a specific post processor.

PPR Process Product Resources.

R

retract macro Motion defined for retracting from the operation end point

S

safety plane A plane normal to the tool axis in which the tool tip can move or remain a clearance distance away from the workpiece, fixture or machine.

set up Describes how the part, stock and fixture are positioned on the machine.

spindle speed The angular speed of the machine spindle. Measured in linear or angular units (m/min or rev/min, for example).

stock Workpiece prior to machining by the operations of a part operation.

T

thickness Specifies a thickness of material to be removed by machining. Compare with [offset](#).

tool axis	Center line of the cutter.
tool change	An auxiliary command in the program that corresponds to a change of tool.
tool clash	Area where the tool collided with the workpiece during a rapid move.
tool path	The trajectory that the tool follows during a machining operation.
total depth	The total depth including breakthrough distance that is machined in a hole making operation.

U

undercut	Area where the tool has left material behind on the workpiece.
-----------------	--

Z

zig zag	Machining in which motion is done alternately in one direction then the other. Compare with one way .
----------------	---

Index

[A](#) [C](#) [D](#) [E](#) [F](#) [G](#) [I](#) [L](#) [M](#) [N](#) [O](#) [P](#) [R](#) [S](#) [T](#) [U](#) [Z](#)

A

Angle of Incline

Groove Finishing parameter 

Grooving parameter 


Recessing parameter 

APT import 

APT source generation 

Attack

Grooving parameter 


Recessing parameter 

Roughing parameter 

Auxiliary operation

Copy Transformation 

Machine Rotation 

Machining Axis or Origin 

PP Instruction 

Tool Change 

Axial Depth of Cut

Recessing parameter 

Roughing parameter 


Axial Limit for Chuck Jaws


Roughing parameter 

Axial offset on part

Groove Finishing parameter 

Grooving parameter 

Profile Finishing parameter 

Recessing parameter 

Roughing parameter 




C

CGR file generation 

Change Output Point

Groove Finishing parameter 

Grooving parameter 


Recessing parameter 

Threading parameter


Chip Break

Grooving parameter 

Clearance


Groove Finishing parameter 

Clearance on crest diameter

Threading parameter 

Clearance on stock

Grooving parameter 

Recessing parameter 

Roughing parameter 

Cfile code generation 

Contouring for Outside Corners

Groove Finishing parameter 

Profile Finishing parameter 


Copy-Transformation Instruction 

Corner Processing

Groove Finishing parameter 

Profile Finishing parameter 

CUTCOM

Groove Finishing parameter 


Profile Finishing parameter 





D

Depth of cut

Threading parameter 



direct axis system 

direct machining axis system 

Documentation generation 




E

Edit Parameters dialog box  

End Limit


Groove Finishing parameter 


Profile Finishing parameter 

Roughing parameter 


Threading parameter 


End Limit Clearance

Groove Finishing parameter 

Profile Finishing parameter 

Roughing parameter 

Threading parameter 

External Groove Finishing 

External Grooving 

External Profile Finishing 

External Recessing 


External Roughing 

External Threading 



F

Face

Roughing mode  

Face Roughing  

Feeds and Speeds

Groove Finishing parameter 


Grooving parameter 

Profile Finishing parameter 

Recessing parameter 

Roughing parameter 

First passes

Threading parameter 

First Plunge

Grooving parameter 

Follow

Sequential Machining motion 

Follow Tool Motion 

Frontal Groove Finishing 

Frontal Grooving 

Frontal Profile Finishing 


Frontal Recessing 

Frontal Roughing 




G

Go Delta

Sequential Machining motion 

Go Delta Motion 

Go InDirv

Sequential Machining motion 


Go InDirv Tool Motion 

Go Standard

Sequential Machining motion 

Go Standard Tool Motion 

Go-Go


Sequential Machining motion 

Go-Go Tool Motion 

Gouging Safety Angle


Grooving parameter 

Recessing parameter 

Groove Finishing operation  

Groove Finishing parameter

Angle of Incline 

Axial offset on part 

Change Output Point 

Clearance 

Contouring for Outside Corners 


Corner Processing 

CUTCOM 

End Limit 

End Limit Clearance 

Feeds and Speeds 

Lead-in 


Lift-off 

Machining Direction 

Machining Tolerance 


Orientation 

Overlap 

Radial offset on part 

Start Limit 

Start Limit Clearance 



Thickness on part 

Tool Compensation 

Under Spindle Axis Machining 

Grooving by Level


Grooving parameter 

Grooving operation  

Grooving parameter


Angle of Incline 

Attack 

Axial offset on part 

Change Output Point 

Chip Break 

Clearance on stock 

Feeds and Speeds 










First Plunge 

Gouging Safety Angle 











Grooving by Level 

Lead-in 


Lift-off 

Machining Tolerance 
Maximum Depth of Cut 
Next Plunges 
Orientation 
Part Contouring 
Radial offset on part 
Thickness on part 
Tool Compensation 
Under Spindle Axis Machining 




Inclined Groove Finishing 
Inclined Grooving 
Inclined Recessing 
insert holder 
Internal Groove Finishing 
Internal Grooving 
Internal Profile Finishing 
Internal Recessing 
Internal Roughing 
Internal Threading 




Last passes
 Threading parameter 
Lead-in




Groove Finishing parameter 

Grooving parameter 


Profile Finishing parameter 

Recessing parameter 

Roughing parameter 

Threading parameter 

Leading Safety Angle

Profile Finishing parameter 

Recessing parameter 


Roughing parameter 

Lift-off


Groove Finishing parameter 

Grooving parameter 

Profile Finishing parameter 

Recessing parameter 

Roughing parameter 


Threading parameter 

Local Information  

Location

Profile Finishing parameter 

Roughing parameter 

Threading parameter 

Longitudinal


Roughing mode  

Longitudinal Roughing  




M


Machine Rotation 

Machining Axis or Origin 

Machining Direction

 Groove Finishing parameter 

 Profile Finishing parameter 


 Recessing parameter 

 Roughing parameter 


Machining Process, Apply 

Machining Process, Create 

Machining spindle speed


 Threading parameter 

Machining Tolerance

 Groove Finishing parameter 

 Grooving parameter 

 Profile Finishing parameter 

 Recessing parameter 

 Roughing parameter 

Manufacturing Program 

Maximum Depth of Cut

 Grooving parameter 

 Recessing parameter 

 Roughing parameter 

Maximum Machining Radius


 Roughing parameter 

Minimum Machining Radius


 Roughing parameter 



N

NC code generation 

Next Plunges

 Grooving parameter 

Nominal diameter

 Threading parameter 

Number of passes

 Threading parameter 


Number of threads

 Threading parameter 




O


One Way


 Recessing mode 


One Way Recessing 

Orientation


 Groove Finishing parameter 


 Grooving parameter 


 Profile Finishing parameter 

 Recessing parameter 


 Roughing parameter 

 Threading parameter 

output point, definition 

output point, examples 


Overlap

 Groove Finishing parameter 



P

Parallel Contour

Recessing mode 


Roughing mode  


Parallel Contour Recessing 


Parallel Contour Roughing  

Part Contouring


Grooving parameter 

Recessing parameter 


Roughing parameter 

Part Operation 


Plunge

Recessing parameter 

Plunge Angle


Roughing parameter 



Plunge Distance

Roughing parameter 


PP Instruction 

Process List 


Product List 

Profile Finishing operation  

Profile Finishing parameter


Axial offset on part 
















Contouring for Outside Corners 

Corner Processing 

CUTCOM 

End Limit 


End Limit Clearance 

Feeds and Speeds 
Lead-in 
Leading Safety Angle 
Lift-off 
Location 
Machining Direction 
Machining Tolerance 
Orientation 
Radial offset on part 
Recess Machining 
Start Limit 
Start Limit Clearance 
Thickness on part 
Tool Compensation 
Trailing Safety Angle 
Under Spindle Axis Machining 




R

Radial Depth of Cut


Recessing parameter 


Roughing parameter 

Radial offset on part

Groove Finishing parameter 


Grooving parameter 

Profile Finishing parameter 

Recessing parameter 

Roughing parameter 

Recess Machining

Profile Finishing parameter 

Roughing parameter 

Recessing mode

One Way 

Parallel Contour 


Zig Zag 


Recessing operation  

Recessing parameter


Angle of Incline 

Attack 

Axial Depth of Cut 

Axial offset on part 

Change Output Point 

Clearance on stock 

Feeds and Speeds 

Gouging Safety Angle 

Lead-in 

Leading Safety Angle 

Lift-off 

Machining Direction 

Machining Tolerance 

Maximum Depth of Cut 


Orientation 

Part Contouring 

Plunge 

Radial Depth of Cut 

Radial offset on part 

Thickness on part 

Tool Compensation 

Trailing Safety Angle 

Under Spindle Axis Machining 

Resources List 

rotary direction 

Roughing mode

Face  


Longitudinal  

Parallel Contour  


Roughing operation 


Roughing parameter

Attack 

Axial Depth of Cut 

Axial Limit for Chuck Jaws 

Axial offset on part 

Clearance on stock 

End Limit 

End Limit Clearance 

Feeds and Speeds 

Lead-in 

Leading Safety Angle 

Lift-off 

Location 

Machining Direction 

Machining Tolerance 

Maximum Depth of Cut 

Maximum Machining Radius 

Minimum Machining Radius 

Orientation 

Part Contouring 


Plunge Angle 

Plunge Distance 

Radial Depth of Cut 

Radial offset on part 

Recess Machining 

Thickness on part 

Tool Compensation 

Trailing Safety Angle 

Under Spindle Axis Machining 



S

Sequential Machining motion


Follow 


Go Delta 

Go InDirv 


Go Standard 

Go-Go 

Sequential Machining operation  

setup angle, 180° 

Simulate material removal 

spindle rotary direction 

Spring passes

Threading parameter 

Start Limit


Groove Finishing parameter 

Profile Finishing parameter 

Threading parameter 

Start Limit Clearance

Groove Finishing parameter 

Profile Finishing parameter 

Threading parameter 



T

Thickness on part

Groove Finishing parameter 

Grooving parameter 

Profile Finishing parameter 

Recessing parameter 

Roughing parameter 

Thread depth

Threading parameter 

Thread length

Threading parameter 

Thread Penetration type

Threading parameter 

Thread pitch

Threading parameter 

Thread profile




























Threading parameter 

Thread unit


Threading parameter 

Threading operation  

Threading parameter

- Change Output Point 
- Clearance on crest diameter 
- Depth of cut 
- End Limit 
- End Limit Clearance 
- First passes 
- Last passes 
- Lead-in 
- Lift-off 
- Location 
- Machining spindle speed 
- Nominal diameter 
- Number of passes 
- Number of threads 
- Orientation 
- Spring passes 
- Start Limit 
- Start Limit Clearance 
- Thread depth 
- Thread length 
- Thread Penetration type 
- Thread pitch 
- Thread profile 
- Thread unit 
- Threading type 
- Threads/inch 
- Tool Compensation 

Threading type


Threading parameter 

Threads/inch


Threading parameter 

Tool Assembly in Resource List

edit  

Tool Change 

Tool Compensation

Groove Finishing parameter 

Grooving parameter 

Profile Finishing parameter 

Recessing parameter 

Roughing parameter 


Threading parameter 

tool in operation

edit or select another 

tool in resource list

edit 

Tool path replay 

tool positioning 

Trailing Safety Angle

Profile Finishing parameter 

Recessing parameter 

Roughing parameter 





U

Under Spindle Axis Machining

Groove Finishing parameter 

Grooving parameter 

Profile Finishing parameter 


Recessing parameter 

Roughing parameter 



Z

Zig Zag

Recessing mode 

Zig Zag Recessing 

